



February 12, 2014

ULNRC-06083

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555-0001

10 CFR 73.71(a)(4)

Ladies and Gentlemen:

**DOCKET NUMBER 50-483  
CALLAWAY PLANT UNIT 1  
UNION ELECTRIC CO.  
FACILITY OPERATING LICENSE NPF-30  
LICENSEE EVENT REPORT 2014-001-00  
SECURITY MEASURE SUSPENDED PER CALLAWAY PLANT SECURITY PLAN**

The enclosed licensee event report is submitted in accordance with 10 CFR 73.71(a)(4) to report a July 26-27, 2013, suspension of a security measure. This action was needed to protect the personal health and safety of security force personnel. This action was associated with the event reported to the Nuclear Regulatory Commission on LER 2013-008-00 (ML13268A112).

This letter does not contain new commitments.

Sincerely,

Luke H. Graessle  
Senior Director, Operations Support

Enclosure

~~The enclosure to this letter contains sensitive information.  
Withhold from public disclosure under 10 CFR 2.390.  
Upon removal of the enclosure, this letter is uncontrolled.~~

ULNRC-06083  
February 12, 2014  
Page 2

cc: Mr. Marc L. Dapas  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
Region IV  
1600 East Lamar Boulevard  
Arlington, TX 76011-4511

Senior Resident Inspector  
Callaway Resident Office  
U.S. Nuclear Regulatory Commission  
8201 NRC Road  
Steedman, MO 65077

Mr. Fred Lyon  
Project Manager, Callaway Plant  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Mail Stop O-8B1  
Washington, DC 20555-2738

**Index and send hardcopy to QA File A160.0761**

**Hardcopy:**

Certrec Corporation  
4150 International Plaza Suite 820  
Fort Worth, TX 76109

(Certrec receives ALL attachments as long as they are non-safeguards and may be publicly disclosed.)

**Electronic distribution for the following can be made via LER ULNRC Distribution:**

F. M. Diya  
C. O. Reasoner III  
L. H. Graessle  
B. L. Cox  
S. A. Maglio  
Corporate Communications  
Corporate Oversight  
NSRB Secretary  
T. B. Elwood  
Performance Improvement Coordinator  
Resident Inspectors (NRC)  
STARS Regulatory Affairs  
Mr. John O'Neill (Pillsbury Winthrop Shaw Pittman LLP)  
Missouri Public Service Commission

<b>NRC FORM 366</b> <small>(10-2010)</small>		<b>U.S. NUCLEAR REGULATORY COMMISSION</b>			APPROVED BY OMB: NO. 3150-0104		EXPIRES: 10/31/2013						
<b>LICENSEE EVENT REPORT (LER)</b> (See reverse for required number of digits/characters for each block)					Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.								
1. FACILITY NAME Callaway Plant Unit 1				2. DOCKET NUMBER 05000483		3. PAGE 1 OF 4							
4. TITLE Security measure suspended per Callaway Plant Security Plan													
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED				
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER			
07	26	2013	2014	- 001	- 00	02	12	2014	FACILITY NAME	DOCKET NUMBER			
9. OPERATING MODE  1		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)											
10. POWER LEVEL  100		<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
		<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input checked="" type="checkbox"/> 73.71(a)(4)
		<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input checked="" type="checkbox"/> OTHER Specify in Abstract below or in NRC Form 366A		<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)
12. LICENSEE CONTACT FOR THIS LER													
FACILITY NAME Kenneth Weith							TELEPHONE NUMBER (Include Area Code) 573-676-6111						
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT													
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX				
14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO							15. EXPECTED SUBMISSION DATE						
							MONTH	DAY	YEAR				
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)													
<p>On July 26, 2013, Callaway Plant declared an Unusual Event associated with a fire in the turbine building. (Refer to Event Number 49219 and LER 2013-008 for additional details of the event.)</p> <p>Due to personnel safety concerns associated with the fire, Security suspended some measures for the site protective strategy. This suspension was allowed per Callaway Plant Security Plan section 24.2.</p> <p>The measures were restored when conditions cleared.</p>													