

NRC FORM 591M PART 1 <small>(10-2011) 10 CFR 2.201</small>		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Norwich Cardiac Medicine 130 New London Turnpike Norwich, CT 06360 REPORT NUMBER 2014-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER 030-38621	4. LICENSE NUMBER 06-35046-01	5. DATE OF INSPECTION February 14, 2014	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the Inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the Inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

Condition 15 of NRC License No. 06-35046-01 requires, in part, that the licensee shall conduct its program in accordance with statements, representations, and procedures contained in the application dated February 15, 2013 (ADAMS Accession No.: ML13063A122).

Item 10.C1 of the application requires, in part, that the licensee will conduct ambient exposure rate surveys at the end of each day of use in areas where radioactive materials are routinely prepared for use, administered or stored. Item 10.C1 further requires, in part, that the licensee will survey weekly for removable contamination in areas where radioactive materials are routinely prepared for use, administered or stored.




Contrary to the above, on December 20, 2013, and January 15, 2014, the licensee did not conduct the required end of the day ambient surveys. Furthermore, the licensee did not conduct the required weekly survey for contamination on December 20, 2014.

This is a Severity Level IV violation. (Section 6.3)

As a corrective action, licensee management committed to performing the required surveys by verifying their completion before the technician left for the day.

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	JAS CHAKRABARTI		2/28/14
NRC INSPECTOR	Shawn W. Seeley		2/26/14
BRANCH CHIEF	James P. Dwyer		3/4/14

*NRC FORM 591M PART 1 (10-2011) (RI Rev. 06/04/2012) G:\WordDocs\Current\Nrsp Record\R06-35046-01.2014001.591M-Part1-Public.doc

SUNSI Review Completed By:


SWS/RA1

Public Non-Sensitive

This document becomes an NRC Official Agency Record once it is signed by the Branch Chief