

**From:** [Tripp, Lester](#)  
**To:** [wbutler@wheelinghospital.org](mailto:wbutler@wheelinghospital.org)  
**Cc:** [Nguyen, Janice](#)  
**Subject:** Request for Additional Information  
**Date:** Thursday, March 20, 2014 9:13:00 AM

---

Licensee Name: Wheeling Hospital, Inc.  
License No.: 47-05322-02  
Docket No.: 03012570  
Mail Control No.: 582254

Dear Dr. Butler:

Please provide the following information:

- 1) Confirm the dose rate measurements performed in surrounding areas for 35.300 and 35.400 inpatient rooms meet public dose limits.
- 2) Confirm that the licensee doesn't have any Yttrium-90 microspheres in storage.
- 3) Confirm that radiation monitoring instrumentation that will be used to measure contamination surveys is sensitive to 200 dpm.
- 4) Confirm that HDR emergency equipment is available (i.e. shielded storage container, remote handling tools, and wire cutters)
- 5) Please submit revised daily HDR spot check procedures to include: verification of source exposure indicator light on the remote afterloader unit; viewing and intercom system in each HDR facility; and verification that emergency response equipment is present. Please include acceptance criteria for checking the clock (date and time) in the unit's computer.

Thanks,

Lester