

Southern California Edison Company

P. O. BOX 8500  
2244 WALNUT GROVE AVENUE  
ROSEMEAD, CALIFORNIA 91770

REGULATORY DOCKET FILE COPY

SC

JACK B. MOORE  
VICE PRESIDENT

TELEPHONE  
213-572-2292

August 30, 1978

Mr. R. H. Engelken, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region V  
Suite 202, Walnut Creek Plaza  
1990 North California Boulevard  
Walnut Creek, California 94596

1978 SEP 19 10 3 16  
RECEIVED  
NRC  
REGION V  
SERVICES

Dear Mr. Engelken:


Subject: Docket Nos. 50-361 and 50-362  
San Onofre Nuclear Generating Station, Units 2 & 3

This letter is submitted in accordance with 10CFR50.55(e) in order to inform you that we will implement for San Onofre Units 2 and 3 corrective action involving the Control Element Drive Mechanism nozzle cones which has been determined to be required by Combustion Engineering. Details concerning this corrective action are provided in a 10CFR50.55(e) report from Arkansas Power & Light Company to NRC Region IV dated April 19, 1978.

The corrective action for San Onofre Units 2 and 3 will be completed during construction activities prior to final assembly of system components.

If you have any questions regarding this report, we would be pleased to discuss this matter with you at your convenience.

Very truly yours,



cc: Dr. Ernst Volgenau (NRC, Director I&E)

782020046

Bo's 10