

## UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

September 25, 1978



Mr. R. J. Sero Manager Systems Safety Monroeville Nuclear Center P. O. Box 355 Pittsburgh, Pennsylvania 15230

Dear Mr. Sero:

We have recently reviewed the safety implications of a Technical Specification error in allowable pressurizer heatup rate for several operating plants using Westinghouse nuclear steam supply systems. Westinghouse had originally recommended using a heatup rate of  $200^{\circ}\text{F/hr}$ . However, Westinghouse reported that this was in error and that a heatup rate must be limited to  $100^{\circ}$  F/hr.

As discussed with Messrs. F. Gigliotti and D. Dudek of your staff on September 13, 1978, we request that you confirm in writing that you are performing an audit review of the stress analyses for components of the reactor coolant pressure boundary to assure that no similar inadvertent errors exist that could adversely affect safe plant operation or require further restrictions to be imposed in the Technical Specifications for plants using Westinghouse NSSSs.

We request that, within 15 days of receipt of this letter you provide us with your confirmation and your schedule for completing this audit review. A prompt response will allow us to resolve this matter in a timely manner.

Sincerely,

A. Schwencer, Chief

Operating Reactors Branch #1 Division of Operating Reactors

Aug 1 0 1 4 1 23 4