NRC FORM 591M PART 1 (07-2012)* 10 CFR 2:201  SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
1. LICENSEE/LOCATION INSPECTED: Bausch & Lomb 8507 Pelham Road Greenville, South Carolina 29615-9598		NRC/REGIONAL OFFICE  U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
REPORT NUMBER 2014-0  3. DOCKET NUMBER	4. LICENSE NUMBER		5. DATE OF INSPECTION	 N
		MMSS-03	April 28, 2014	
LICENSEE:  The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X				
I hereby state that, within 30 days, the		orrective Actions ector will be taken to correct	the violations identified. Th	nis statement of
corrective actions is made in accordant date when full compliance will be achieved.	nce with the requirements of 10 CFR	2.201 (corrective steps alrea	ady taken, corrective steps v	which will be taken,
Title	Printed Name	· 	Signature	Date
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR	Scott Wilson		/RA/	5/20/2014
BRANCH CHIEF	Blake Welling		/RA/	5/20/2014
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\WordDocs\Current\Insp Record\RAS-NMMSS-03.2014001.591M-Part1.doc				
SUNSI Review Completed By:	/RA/ SWilson		X Public X	Non-Sensitive