



LER CONTINUATION - RO# 79-029

Facility: HBR-2

Event Date: 8-14-79

CAUSE DESCRIPTION AND ANALYSIS:

On August 14, 1979, between 0100 and 0530, the hourly inspections of the fire zones were not performed as required by proposed Technical Specifications, Paragraph 3.14.1.2.b. The contractor person who had been assigned to perform these inspections failed to conduct them properly during this time period. Upon investigation, the Shift Foreman learned from the individual that he felt sick and "could not move around very well".

CORRECTIVE ACTION:

The Shift Foreman sternly explained the importance of these hourly inspections and the responsibilities of the fire patrol. He further explained the importance of informing the Shift Foreman if a replacement person is required for any reason. The patrols were resumed and performed properly for the remainder of the shift.

CORRECTIVE ACTION TO PREVENT FURTHER OCCURRENCE:

If the present contractor personnel prove themselves to be unreliable, they are replaced by other, more reliable personnel. No other corrective action is deemed necessary at this time.