

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8005080351 DOC DATE: 80/04/21 NOTARIZED: NO DOCKET #  
 FACIL:50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261  
 AUTH.NAME AUTHOR AFFILIATION  
 STARKEY,R.B. Carolina Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: RO:on 800418,while performing eddy current insp of steam generator B data evaluation revealed sufficient number of defective tubes to result in C-3 results classification of original insp sample.Insp scope was expanded.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1-----  
 TITLE: Incident Reports

NOTES:-----

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
ACTION:	05 BC ORB #1	4				
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	22 REAC SAFT BR	1	1
	23 ENGR BR	1	1	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 AD/SITE ANAL	1	1
	27 OPERA LIC BR	1	1	28 ACDENT ANLYS	1	1
	29 AUX SYS BR	1	1	AD/ORP-DOR	1	1
	AEOD	10	10	BERLINGER,C.	3	3
	DOUG MAY-TERA	1	1	HANAUER,S.	1	1
	JORDAN,E./IE	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

TOTAL NUMBER OF COPIES REQUIRED: LTTR 61 ENCL 0



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT  
Post Office Box 790  
Hartsville, South Carolina 29550

April 21, 1980

Robinson File No: 2-0-4-a-3

SERIAL:RSEP/80-584

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

In accordance with Plant Technical Specification 6.9.2.a(3), the following event is reported.

At approximately 1300 hours on April 18, 1980, while performing eddy current inspection of "B" steam generator as required by Technical Specification 4.2.5.1.4.e (Reference Letter from R. B. Starkey, Jr. to James P. O'Reilly dated April 15, 1980), Carolina Power and Light Company was notified that data evaluation had revealed a sufficient number of defective tubes to result in a C-3 results classification of the original inspection sample. The inspection scope was subsequently expanded as required by Technical Specification Table 4.2-2 and this inspection is currently in progress.

Mr. R. Saur of Region II of the Nuclear Regulatory Commission was notified by telephone at 1730 hours on April 18, 1980. This notification meets the requirements of Technical Specification 6.9.2.a(3) of prompt notification.

Very truly yours,

R. B. Starkey, Jr.  
General Manager  
H. B. Robinson S. E. Plant

EVP:pb

A002  
S  
1/6

ORIGINAL COPY