



Carolina Power & Light Company  
February 14, 1978

*Central File*  
*50-261*

FILE: NG-3513 (R)

SERIAL: GD-78-398

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II, Suite 1217  
230 Peachtree Street, N.W.  
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2  
DOCKET NO. 50-261  
LICENSE NO. DPR-23  
RESPONSE TO IE BULLETIN 78-02

Dear Mr. O'Reilly:

IE Bulletin 78-02, January 30, 1978, requested information on the environmental qualification of unprotected terminal blocks used inside containment. Investigation and inspection at the H. B. Robinson Plant has shown that no unprotected terminal blocks are used in any system which must function in a post-accident environment. This information was provided to your staff by telephone on January 31, 1978.

Yours very truly,

E. E. Utley  
Senior Vice President  
Power Supply Group

CSB:as\*

cc: Mr. E. G. Case  
Mr. E. Volgenau