## October 9, 1991

NOTE TO: Files

FROM: Engineering Branch

SUBJECT: ERRATA LETTER FOR NOTICE OF VIOLATION (NRC INSPECTION

REPORT NO. 50-261/89-201)

The subject inspection report was transmitted to you by our letter, dated October 4, 1991. It has come to our attention that the Notice of Violation, was transmitted with typos. We have enclosed a corrected copy of the letter.

Docket No. 50-261 License No. DPR-23

Carolina Power and Light Company
ATTN: Mr. Lynn W. Eury
Executive Vice President
Power Supply
P. 0. Box 1551
Raleigh, NC 27602

Gentlemen:

SUBJECT: NOTICE OF VIOLATION

(NRC INSPECTION REPORT NO. 50-261/89-201)

This refers to the inspection conducted by J. Jacobson of this office on June 10-14, 1991. The inspection included a review of activities authorized for your Robinson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the report.

Areas examined during the inspection are identified in the report issued to you on July 25, 1991. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements. The violation described in the enclosed Notice is similar to a violation contained in the Notice sent to you by our letter dated September 22, 1989. Recurring violations are of particular concern because the NRC expects licensees to learn from their past failures and to take effective corrective actions. Although NRC does not normally consider monetary civil penalties for Severity Level IV violations, the Enforcement Policy states that such penalties may be imposed for Severity Level IV violations that are similar to previous violations for which the licensee did not take effective corrective action. In this case, we have decided not to hold an enforcement conference and not to propose a civil penalty because after this issue was brought to your attention, the valve in question was demonstrated to be operable.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

(cc w/encl cont'd)
Mr. H. Ray Starling
Manager - Legal Department
P. O. Box 1551
Raleigh, NC 27602

H. A. Cole Special Deputy Attorney General State of North Carolina P. O. Box 629 Raleigh, NC 27602

Robert Gruber
Executive Director
Public Staff - NCUC
P. O. Box 29520
Raleigh, NC 27626-0520

 J. D. Kloosterman, Director Regulatory Compliance
 H. B. Robinson Steam Electric Plant
 P. O. Box 790
 Hartsville, SC 29550

bcc w/encl:
Document Control Desk
H. Christensen, RII
R. Lo, NRR
B. K. Grimes, NRR

NRC Resident Inspector U.S. Nuclear Regulatory Commission Route 5, Box 413 Hartsville, SC 29550

\*FOR PREVIOUS CONCURRENCES - SEE ATTACHED COPY

(cc w/encl cont'd)
Mr. H. Ray Starling
Manager - Legal Department
P. O. Box 1551
Raleigh, NC 27602

H. A. Cole Special Deputy Attorney General State of North Carolina P. O. Box 629 Raleigh, NC 27602

Robert Gruber Executive Director Public Staff - NCUC P. O. Box 29520 Raleigh, NC 27626-0520

J. D. Kloosterman, Director Regulatory Compliance H. B. Robinson Steam Electric Plant P. O. Box 790 Hartsville, SC 29550

bcc w/encl: Document Control Desk H. Christensen, RII R. Lo, NRR B. K. Grimes, NRR

NRC Resident Inspector U.S. Nuclear Regulatory Commission Route 5, Box 413 Hartsville, SC 29550

RII:DRS CJulian:er 09//0/91 RII:DRS

AGibson 09/ /91 RII:DRP

EMerschoff 09/ /91 RII:EICS

GJenkins 09/ /91