

PRIORITY 1
(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9503010209 DOC.DATE: 95/02/23 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
 AUTH.NAME AUTHOR AFFILIATION
 KRICH, R.M. Carolina Power & Light Co.
 RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC request made in 941222 meeting w/WOG, for
 utils w/Westinghouse mechanical SG tube plugs mfg from Alloy
 600 TT to perform assessment of plugs integrity &
 suitability for continued operation.

DISTRIBUTION CODE: A023D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Westinghouse Alloy 600 Issues

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 LA	1 1	PD2-1 PD	1 1
	MOZAFARI, B	1 1		
INTERNAL:	FILE CENTER 01	1 1	NRR/DE/EMCB	1 1
	NRR/DRPE/PD21	1 1	NRR/DSSA/SRXB	1 1
	NUDOCS ABSTRACT	1 1	OGC/HDS3	1 1
EXTERNAL:	NRC PDR	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
 DESK, ROOM P1-37 (EXT 504-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 10 ENCL ~~10~~ 0

MA4

P
R
I
O
R
I
T
Y

1
D
O
C
U
M
E
N
T



Carolina Power & Light Company
Robinson Nuclear Plant
3581 West Entrance Road
Hartsville SC 29550

Robinson File No.: 13510
Serial: RNP-RA/95-0026

FEB 23 1995

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
RESPONSE TO REQUEST FOR INFORMATION BY NRC MADE IN DECEMBER 22, 1994, MEETING WITH WESTINGHOUSE OWNERS GROUP REGARDING STEAM GENERATOR TUBE PLUGS

Gentlemen:

This letter is submitted in response to a request by Mr. Brian Sheron, NRC, made at a meeting with the Westinghouse Owners Group on December 22, 1994, for utilities with Westinghouse mechanical steam generator tube plugs manufactured from Alloy 600 TT to perform an assessment of their integrity and suitability for continued operation.

The H. B. Robinson Steam Electric Plant (HBRSEP), Unit No. 2 does not have any Westinghouse mechanical steam generator tube plugs manufactured from Alloy 600 TT that have not already been repaired or replaced. The only two plugs of this type that were installed were repaired using the "plug-in-plug" process in November 1990. The repair process utilized is considered to be a permanent repair in accordance with NRC Bulletin 89-01, "Failure of Westinghouse Steam Generator Tube Mechanical Plugs," and no further action is planned for HBRSEP.

Questions regarding this matter may be referred to Mr. K. R. Jury at (803) 857-1363.

Very truly yours,

R. M. Krich
Manager - Regulatory Affairs

9503010209 950223
PDR ADDCK 05000261
P PDR

AD23 | 0

RNP-RA/95-0026

Page 2 of 2

c: Mr. S. D. Ebneter, Regional Administrator, USNRC, Region II
Ms. B. L. Mozafari, USNRC Project Manager, HBRSEP
Mr. W. T. Orders, USNRC Senior Resident Inspector, HBRSEP