

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9902050095	DOC.DATE: 99/01/29	NOTARIZED: NO	DOCKET #
FACIL:50-261	H.B. Robinson Plant, Unit 2, Carolina Power & Light C		05000261
AUTH.NAME	AUTHOR AFFILIATION		
WALT,T.D.	Carolina Power & Light Co.		
RECIP.NAME	RECIPIENT AFFILIATION		
	Records Management Branch (Document Control Desk)		

SUBJECT: Forwards LER 98-003-01, re reactor trip due to inadvertent closure of turbine governor valves. Addl info re described event was identified during investigation of 981017, automatic reactor trip at Unit 2.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE:
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
PD2-1 PD	1	1	SUBBARATNAM	1	1
INTERNAL: AEOD/SPD/RAB	2	2	AEOD/SPD/RRAB	1	1
<u>FILE CENTER</u>	1	1	NRR/DE/ECGB	1	1
NRR/DE/EELB	1	1	NRR/DE/EMEB	1	1
NRR/DRCH/HICB	1	1	NRR/DRCH/HOHB	1	1
NRR/DRCH/HQMB	1	1	NRR/DRPM/PECB	1	1
NRR/DSSA/SPLB	1	1	RES/DET/EIB	1	1
RGN2 FILE 01	1	1			
EXTERNAL: L ST LOBBY WARD	1	1	LITCO BRYCE, J H	1	1
NOAC POORE, W.	1	1	NOAC QUEENER, DS	1	1
NRC PDR	1	1	NUDOCS FULL TXT	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 22



Carolina Power & Light Company

Robinson Nuclear Plant
3581 West Entrance Road
Hartsville SC 29550

Robinson File No: 13510C
Serial: RNP-RA/99-0006

JAN 29 1999

United States Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23

LICENSEE EVENT REPORT 1998-003-01 REACTOR TRIP
DUE TO INADVERTENT CLOSURE OF TURBINE GOVERNOR VALVES

Dear Sir or Madam:

The attached revision to Licensee Event Report (LER) 1998-003-00 is submitted in accordance with the requirements of 10 CFR 50.73. Additional information relative to the described event was identified during the investigation of the October 17, 1998, automatic reactor trip at HBRSEP, Unit No. 2 (LER 1998-005-00). If you have any questions regarding this matter, please contact Mr. R. L. Warden, Manager, Regulatory Affairs.

Sincerely,

T. D. Walt
Plant General Manager

MSL/msl
Attachment

c: Mr. L. A. Reyes, NRC, Region II
Mr. R. Subbaratnam, NRR, NRC
NRC Resident Inspector, HBRSEP

9902050095 990129
PDR ADOCK 05000261
S PDR

030002