

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9508020102 DOC.DATE: 95/07/26 NOTARIZED: NO DOCKET #
FACIL:50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
AUTH.NAME AUTHOR AFFILIATION
KRICH,R.M. Carolina Power & Light Co.
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Revises corrective action completion date re insp rept
50-261/95-12.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 2
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 PD	1 1	MOZAFARI, B	1 1
INTERNAL:	AEOD/DEIB	1 1	AEOD/SPD/RAB	1 1
	AEOD/TTC	1 1	DEDRO	1 1
	FILE CENTER	1 1	NRR/DISP/PIPB	1 1
	NRR/DORS/OEAB	1 1	NRR/DRCH/HHFB	1 1
	NUDOCS-ABSTRACT	1 1	OE DIR	1 1
	OGC/HDS3	1 1	RGN2 FILE 01	1 1
EXTERNAL:	LITCO BRYCE, J H	1 1	NOAC	1 1
	NRC PDR	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL
DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM
DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 17 ENCL 20



Carolina Power & Light Company
Robinson Nuclear Plant
3581 West Entrance Road
Hartsville SC 29550

RNP File No: 13510E
Serial: RNP-RA/95-0143

JUL 26 1995

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT (HBRSEP), UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
NRC INSPECTION REPORT NO. 50-261/95-12
REVISION TO CORRECTIVE ACTION COMPLETION DATES

Gentlemen:

The purpose of this letter is to revise a corrective action completion date. A reply to NRC Notice of Violation RII-95-12-03-SL4 was provided by letter dated June 19, 1995. A corrective action identified within the reply stated that, "Procedure PM-402 will be revised to include breaker timing testing as part of PM testing. In addition, procedure Preventative Maintenance (PM)-163, "Inspection and Testing of Circuit Breakers for 480 Volt Bus E-2," will also be revised to include breaker timing testing." We committed to full compliance by July 26, 1995.

Implementation of the corrective action in response to this NRC violation requires that our engineering personnel provide the timing requirements based on vendor recommendations. The applicable vendor(s) have been unable to provide the necessary information to support a timely revision to procedures PM-163 and PM-402 in order to meet the committed date. To allow sufficient time for the development and implementation of the timing requirements, the completion date for this action is requested to be extended until September 22, 1995. The revised commitment date will allow engineering to obtain the necessary vendor recommendations for timing requirements and incorporate them into the affected procedures in a reasoned and methodical manner. As an interim measure, breaker timing tests are being performed utilizing a generic method required in procedure Maintenance Management Manual (MMM)-003, "Maintenance Work Requests."

020020

9508020102 950726
PDR ADOCK 05000261
Q PDR

Highway 151 and SC 23 Hartsville SC

EE01
1/0

United States Nuclear Regulatory Commission
Serial: RNP-RA/95-0143
Page 2 of 2

Questions regarding this matter may be referred to Mr. A. L. Garrou at (803) 383-1544.

Very truly yours,



R. M. Krich
Manager - Regulatory Affairs

DTG:dtg

c: Mr. S. D. Ebnetter, Regional Administrator, USNRC, Region II
Ms. B. L. Mozafari, USNRC Project Manager, HBRSEP
Mr. W. T. Orders, USNRC Senior Resident Inspector, HBRSEP