

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8209220198 DOC. DATE: 82/09/16 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Light 05000261
 AUTH. NAME AUTHOR AFFILIATION
 UTLEY, E.E. Carolina Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 VARGA, S.A. Operating Reactors Branch 1

SUBJECT: Forwards "Steam Generator Repair Rept," preliminary assessment of repair activities. *566 RPA*

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 10 SIZE: 2 + 52
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME		LTR	ENCL
	NRR ORB1 BC	01	7	4				
INTERNAL:	ELD/HDS1		1	0	NRR/DHFS DEPY08		1	0
	NRR/DL DIR		1	1	NRR/DL/ORAB		1	0
	NRR/DSI/RAB		1	1	<u>REG FILE</u>	04	1	1
	RGN2		1	1				
EXTERNAL:	ACRS	09	6	0	LPDR	03	1	1
	NRC PDR	02	1	1	NSIC	05	1	1
	NTIS		1	1				

Limited Dist.

[Handwritten mark]



Carolina Power & Light Company

September 16, 1982

Office of Nuclear Reactor Regulation
ATTN: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
United States Nuclear Regulatory Commission
Washington, D.C. 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
PRELIMINARY STEAM GENERATOR REPAIR REPORT

Dear Mr. Varga:

As stated in my letter to you dated July 1, 1982, Carolina Power & Light Company (CP&L) is hereby submitting for your review the attached Steam Generator Repair Report. The attached report is CP&L's preliminary assessment of the activities involved in repairing the H. B. Robinson Unit No. 2 (HBR2) steam generators. This preliminary assessment indicates that this repair effort does not involve an unreviewed safety question and that a change to the plant's Technical Specifications is not required.

Because the project plans and design are incomplete, certain information may not be included at this time. As stated previously, it is CP&L's intent to submit the final Steam Generator Repair Report on January 3, 1983. As such, it would be useful if the NRC would provide any comments regarding any phase of this report by November 15, 1982. This would allow CP&L to make the final report as complete a report as possible.

Carolina Power & Light Company is currently pursuing procurement, engineering, and licensing activities to enable it to effect a steam generator repair at a time which is contingent on steam generator performance and ideally would coincide with a refueling outage. At this time, the earliest time that repair could take place is at the refueling outage scheduled to begin in November 1983.

A001
S
1/10


8209220198 820916
PDR ADOCK 05000261
P PDR

Steven A. Varga

- 2 -

Should you require additional information with regard to these activities, or desire a meeting to further discuss or expand upon the information provided, please contact a member of our licensing staff.

Yours very truly,



E. E. Utley
Executive Vice President
Power Supply and
Engineering & Construction

DCS/mf (1085C2T1)
Attachment

cc: Mr. J. P. O'Reilly (NRC-RII)
Mr. G. Requa (NRC)
Mr. Steve Weise (NRC-HBR)