

August 26 1980
AUG 29 12:00

FILE: NG-3513(R)

SERIAL: NO-80-1231

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261
LICENSE NO. DPR-23
RESPONSE TO IE BULLETIN 80-19 - MERCURY-WETTED MATRIX RELAYS

Dear Mr. O'Reilly:

A review of the H. B. Robinson Unit No. 2 Reactor Protection Relay Logic and Safeguards Relay Logic has confirmed that mercury-wetted relays are not used in these systems.

If you have any questions concerning this information, please contact me or a member of my staff.

Yours very truly,

Wary for B.J. Furr

B. J. Furr
Vice President
Nuclear Operations

MVP:CSB:tma*

cc: Mr. N. C. Moseley