REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8905190154 DOC.DATE: 89/05/05 NOTARIZED: NO DOCKET # FACIL:50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261

AUTH.NAME AUTHOR AFFILIATION

LOFLIN, L.I. Carolina Power & Light Co. RECIP. NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Submits results of capacity discharge test performed on facility station batteries during latest refueling outage.

DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR L ENCL SIZE: TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES:

	RECIPIENT	COPIES	RECIPIENT	COPIES
	ID CODE/NAME	LTTR ENCL	ID CODE/NAME	LTTR ENCL
	PD2-1 LA LO,R	1 1	PD2-1 PD	5 5
INTERNAL:	AEOD/DSP/TPAB NRR/DEST/MTB 9H OC/LFMB REG FILE 01	1 1 1 1 1 1	NRR/DEST/MEB 9H NUDOCS-ABSTRACT OGC/HDS1 RES/DSIR/EIB	1 1 1 1 1 6
EXTERNAL:	EG&G BROWN,B	1	EG&G ROCKHOLD,H	1 1
	LPDR	1	NL 007 HEMMING	1 1
	NRC PDR	1	NSIC	1 1

mpiet



Carolina Power & Light Company

SERIAL: NLS-89-132

MAY 0 5 1989

United States Nuclear Regulatory Commission ATTENTION: Document Control Desk Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2 DOCKET NO. 50-261/LICENSE NO. DPR-23 BATTERY TEST RESULTS

Gentlemen:

This letter provides the results of the capacity discharge test performed on the H. B. Robinson Steam Electric Plant, Unit No. 2 station batteries during the latest refueling outage as discussed during the October 20-22, 1988 meeting between CP&L and NRC Electrical Systems Branch representatives. The surveillance test performed was conducted in accordance with the recommendations of IEEE 450-1980.

The results presented are compared with for 1987 refueling outage test results.

Capacity (%) Based On Total Battery Voltage (MST-920)

Refueling Outage	A-Battery	B-Battery
1988	103	102
1987	107	101

These results were compared with and met the MST-920, "Station Battery Performance Capacity Test" acceptance criteria as follows:

- 1. The percent battery capability decrease from the average of the previous tests was less than the maximum 10 percent limit.
- 2. The battery capacity was greater than the 90% minimum limit.

The acceptance criteria for the test were met and the batteries are operable. The current battery test results are being evaluated to determine when the next performance test should be conducted.

8905190154 890505 PDR ADOCK 05000261 P PNU



A047

Document Control De NLS-89-132 / Page 2

Questions regarding this matter may be referred to Mr. R. W. Prunty at (919) 546-7318.

Yours very truly,

Manager

Nuclear Licensing Section

JSK/crs (328CRS)

Enclosure

cc: Mr. S. D. Ebneter

Mr. L. Garner (NRC - HBR)

Mr. R. Lo