ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

CESSION NBR:8811220100 DOC.DATE: 88/11/16 NOTARIZED: NO DOCKET # FACIL:50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261 AUTH.NAME AUTHOR AFFILIATION ERNST,M.L. Region 2, Ofc of the Director RECIP.NAME RECIPIENT AFFILIATION UTLEY,E.E. Carolina Power & Light Co. R

SUBJECT: Forwards partially withheld Insp Rept 50-261/88-32 on 881102-03. Violations noted.

DISTRIBUTION CODE: IE04D COPIES RECEIVED:LTR l ENCL l SIZE: X + lTITLE: Safeguards Inspection Rpt/NOV Response (50 DKT)-Publicly Available

NOTES:

	RECIPIENT ID CODE/NAME PD2-1 LA LO,R	COPIES LTTR ENCL 1 0 1 1	RECIPIENT ID CODE/NAME PD2-1 PD	COPIES LTTR ENCL 1 1	י נ ן
INTERNAL:	AEOD/DOA NRR/DRIS/SIB 9A NUDOCS-ABSTRACT RGN2 FILE 01	1 0 1 1 1 1 1 1	NRR/DRIS/SGB 9D NRR/DMAS/ILRB12 REG FILE 02	1 1 1 0 1 1	1
EXTERNAL:	LPDR NSIC	1 1 1 1	NRC PDR	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 13 ENCL 10

D D S

I

D

S

D

S

R

SAFEGUARDS INFORMATION

NOV 1 6 1988

Docket No. 50-261 License No. DPR-23

SAFEGUARDS INFORMATION REMOVED

Carolina Power and Light Company ATTN: Mr. E. E. Utley Senior Executive Vice President Power Supply and Engineering and Construction P. O. Box 1551 Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-261/88-32

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by J. D. Ennis on November 2-3, 1988. The inspection included a review of activities authorized for your H. B. Robinson facility and a review of circumstances surrounding a physical security event identified and reported by the licensee on October 28, 1988. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

The inspection findings indicate that certain activities appeared to violate NRC requirements. The violation described in the enclosed Inspection Report is under consideration for escalated enforcement action. Accordingly, no Notice of Violation is being issued at this time, and no response to this letter is required. However, please be advised that the number and characterization of violations described in the enclosed Inspection Report may change as a result of further NRC review. An Enforcement Conference to discuss this violation has been scheduled for December 8, 1988. You will be advised by separate correspondence of the results of our deliberations on this matter.

In accordance with 10 CFR 2.790(d) and 10 CFR 73.21, safeguards activities and security measures are exempt from public disclosure. Therefore, the enclosure to this letter, with the exception of the report cover page, which presents a nonexempt summary, will not be placed in the NRC Public Document Room.

8811220100 881116 PDR ADOCK 05000261 Q PDC

IE04 Document transmitted herewith

contains sensitive unclassified UU information. When separated from enclosures, this document is decontrolled.

SAFEGUARDS INFORMATION

SAFECHADOS INFORMATION

Carolina Power and Light Company 2

Should you have any questions concerning this letter, please contact us.

Sincerely, 640N Malcolm L. Ernst o^N Acting Regional Administrator

Enclosure: NRC Inspection Report 50-261/88-32 (Safeguards Information)

cc w/encl: C. R. Dietz, Manager Robinson Nuclear Project Department R. E. Morgan, Plant General Manager

cc w/Inspection Summary: State of South Carolina

bcc w/encl: NRR/DRIS/SB

bcc w/Inspection Summary: Document Control Desk (RIDS IEO4), 016 NRC Resident Inspector

