REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

FCESSION NBR:8901090274 DOC.DATE: 88/12/22 NOTARIZED: NO DOCKET #
FACIL:50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
AUTH.NAME AUTHOR AFFILIATION
HERDT,A.R. Region 2, Ofc of the Director
RECIP.NAME RECIPIENT AFFILIATION
UTLEY,E.E. Carolina Power & Light Co.

SUBJECT: Forwards Insp Rept 50-261/88-14 on 881128-1202.No violations or deviations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR / ENCL / SIZE: 2+12
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

.1	RECIPIENT ID CODE/NAME PD2-1 PD	COPI LTTR 1	ES ENCL 1	RECIPIENT ID CODE/NAME LO,R	COPIES LTTR ENCL 1 1	1
INTERNAL:	AEOD DEDRO NRR/DEST DIR NRR/DLPQ/QAB 10 NRR/DREP/EPB 10 NRR/DRIS DIR 9A NUDOCS-ABSTRACT OGC/HDS1 RGN2 FILE 01	1 1 1 1 1 1 1	1 1 1 1 1 1 1	AEOD/DEIIB NRR SHANKMAN,S NRR/DLPQ/PEB 11 NRR/DOEA DIR 11 NRR/DREP/RPB 10 NRR/PMAS/ILRB12 OE LIEBERMAN,J REG FILE 02	1 1 1 1 1 1 2 2 1 1 1 1 1 1	I I S
TERNAL:	LPDR NSIC	1	1	NRC PDR RESL MARTIN, D	1 1 1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

eet

Yellow.

Docket No. 50-261 License No. DPR-23

Carolina Power and Light Company

ATTN: Mr. E. E. Utley

Senior Executive Vice President Power Supply and Engineering

and Construction

P. O. Box 1551 Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 5G-261/88-14

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by N. Economos on November 28 - December 2, 1988. The inspection included a review of activities authorized for your Robinson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Alan R Herdt, Chief Engineering Branch Division of Reactor Safety

Enclosure: NRC Inpection Report

cc w/encl: (See page 2)

8901090274 881222 PDR ADUCK 05000261 PDC 1/1

DCC w/encl: NRC Resident Inspector DRS Technical Assistant Document Control Desk

NEconomos:ser 12//9/88 (R] I /JB1ake /12/__//88 RII PFredrickson 12/21/88