

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8901170187 DOC.DATE: 89/01/04 NOTARIZED: NO DOCKET #  
 FACIL:50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261  
 AUTH.NAME AUTHOR AFFILIATION  
 HERDT,A.R. Region 2, Ofc of the Director  
 RECIP.NAME RECIPIENT AFFILIATION  
 UTLEY,E.E. Carolina Power & Light Co.

SUBJECT: Forwards corrected transmittal ltr & rept cover for Insp  
Rept 50-261/88-35.Insp Rept 50-261/88-14 inadvertently used.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1 + 4  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-1 PD	1 1	LO,R	1 1
INTERNAL:	AEOD	1 1	AEOD/DEIIB	1 1
	DEDRO	1 1	NRR SHANKMAN,S	1 1
	NRR/DEST DIR	1 1	NRR/DLPQ/PEB 11	1 1
	NRR/DLPQ/QAB 10	1 1	NRR/DOEA DIR 11	1 1
	NRR/DREP/EPB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/DRIS DIR 9A	1 1	NRR/PMAS/ILRB12	1 1
	NUDOCS-ABSTRACT	1 1	OE LIEBERMAN,J	1 1
	OGC/HDS1	1 1	<u>REG FILE</u> 02	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1	RESL MARTIN,D	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

R  
I  
D  
S  
/  
A  
D  
D  
S  
  
R  
I  
D  
S  
/  
A  
D  
D  
S

JAN 04 1989

*Yellow*

Docket No. 50-261  
License No. DPR-23

Carolina Power and Light Company  
ATTN: Mr. E. E. Utley  
Senior Executive Vice President  
Power Supply and Engineering  
and Construction  
P. O. Box 1551  
Raleigh, NC 27602

Gentlemen:

SUBJECT: ERRATA LETTER FOR NRC INSPECTION REPORT NO. 50-261/88-35

The above subject inspection was transmitted to you by letter, dated December 22, 1988. It has come to our attention that the Inspection Report No. 50-261/88-14 was inadvertently used. A correct transmittal letter and report cover sheet are enclosed. Please delete the superseded letter and report cover sheet and insert the corrected letter and cover sheet with your copy of the report.

If you have any questions concerning this matter, please contact us.

Sincerely,

*For Jerome Blake*  
Alan R. Herdt, Chief  
Engineering Branch  
Division of Reactor Safety

Enclosure:  
As Stated

cc w/encl:  
C. R. Dietz, Manager  
Robinson Nuclear Project Department  
R. E. Morgan, Plant General Manager  
State of South Carolina

bcc w/encl:  
NRC Resident Inspector  
DRS Technical Assistant  
Document Control Desk

RI  
*[Signature]*  
NEconomos:gb  
~~12/188~~  
1/3/89  
*[Signature]*  
Blake  
~~12/13/88~~

8901170187 890104  
PDR ADOCK 05000261  
Q PDC

*IE01*

DEC 22 1988

Docket No. 50-261  
License No. DPR-23

Carolina Power and Light Company  
ATTN: Mr. E. E. Utley  
Senior Executive Vice President  
Power Supply and Engineering  
and Construction

P. O. Box 1551  
Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-261/88-35

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by N. Economos on November 28 - December 2, 1988. The inspection included a review of activities authorized for your Robinson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.


Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

  
For Alan R. Herdt, Chief  
Engineering Branch  
Division of Reactor Safety

Enclosure:  
NRC Inspection Report

cc w/encl: (See page 2)

DEC 22 1988

cc w/encl:

C. R. Dietz, Manager

Robinson Nuclear Project Department

R. E. Morgan, Plant General Manager


State of South Carolina


bcc w/encl:


NRC Resident Inspector

DRS Technical Assistant

Document Control Desk

  
NEconomos:ser  
12/30/88

  
JBlake  
12/30/88

  
PFredrickson  
12/ /88



ENCLOSURE

UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
101 MARIETTA ST., N.W.  
ATLANTA, GEORGIA 30323

DEC 22 1988

Docket No. 50-261  
License No. DPR-23

Carolina Power and Light Company  
ATTN: Mr. E. E. Utley  
Senior Executive Vice President  
Power Supply and Engineering  
and Construction

P. O. Box 1551  
Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-261/88-35

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by N. Economos on November 28 - December 2, 1988. The inspection included a review of activities authorized for your Robinson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

A handwritten signature in dark ink, appearing to read "A. Herdt", written over a horizontal line.

Alan R. Herdt, Chief  
Engineering Branch  
Division of Reactor Safety

Enclosure:  
NRC Inspection Report

cc w/encl: (See page 2)