



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
101 MARIETTA ST., N.W.  
ATLANTA, GEORGIA 30323

Report No.: 50-261/88-35

Licensee: Carolina Power and Light Company  
P. O. Box 1551  
Raleigh, NC 27602

Docket No.: 50-261

License No.: DPR-23

Facility Name: H. B. Robinson

Inspection Conducted: November 28 - December 2, 1988

Inspector:

*J. Blake*  
Nick Economos

12/30/88  
Date Signed

Approved by:

*J. Blake*  
J. B. Blake, Chief  
Materials and Processes Section  
Engineering Branch  
Division of Reactor Safety

12/30/88  
Date Signed

SUMMARY

Scope: This routine unannounced inspection was conducted in the areas of resistance temperature detector (RTD) bypass elimination and service water system piping replacement modifications.

Results: In the areas inspected, no violations or deviations were identified.

Both modifications are being implemented by vendor, e.g. Westinghouse and PCI, respectively. The licensee has dedicated adequate resources/manpower for engineering work monitoring and liaison between the licensee and the vendors. Work quality, material control, training and qualification were found to be consistent with Code and regulatory requirements.

8901170192 890104  
PDR ADDCK 05000261  
Q PDC