

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8903240076 DOC. DATE: 89/03/03 NOTARIZED: NO DOCKET #
 FACIL: 50-261 H.B. Robinson Plant, Unit 2, Carolina Power & Light C 05000261
 AUTH. NAME AUTHOR AFFILIATION
 COLLINS, D.M. Region 2, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION
 UTLEY, E.E. Carolina Power & Light Co.

SUBJECT: Forwards Insp Rept 50-261/89-06 on 890206-09. No violations noted.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+8
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTR	ENCL	ID CODE/NAME	LTR	ENCL	
	PD2-1 PD		1	1	LO,R	1	1	
INTERNAL:	AEOD		1	1	AEOD/DEIIB	1	1	
	DEDRO		1	1	NRR SHANKMAN,S	1	1	
	NRR/DEST DIR		1	1	NRR/DLPQ/PEB 11	1	1	
	NRR/DLPQ/QAB 10		1	1	NRR/DOEA DIR 11	1	1	
	NRR/DREP/EPB 10		1	1	NRR/DREP/RPB 10	2	2	
	NRR/DRIS DIR 9A		1	1	NRR/PMAS/ILRB12	1	1	
	NUDOCS-ABSTRACT		1	1	OE LIEBERMAN,J	1	1	
	OGC/HDS1		1	1	<u>REG FILE 02</u>	1	1	
	RGN2 FILE 01		1	1				
INTERNAL:	LPDR		1	1	NRC PDR	1	1	
	NSIC		1	1				

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 23 ENCL 23

RIDS / ADDS

OFFICIAL

MAR 03 1989

Docket No. 50-261
License No. DPR-23

Carolina Power and Light Company
ATTN: Mr. E. E. Utley
Senior Executive Vice President
Power Supply and Engineering
and Construction
P. O. Box 1551
Raleigh, NC 27602

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-261/89-06

This refers to the Nuclear Regulatory Commission (NRC) inspection conducted by M. T. Lauer on February 6-9, 1989. The inspection included a review of activities authorized for your Robinson facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed Inspection Report.

Areas examined during the inspection are identified in the report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress.

Within the scope of the inspection, no violations or deviations were identified.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

8903240076 890303
PDR ADDCK 05000261
Q PNU

Douglas M. Collins, Chief
Emergency Preparedness and Radiological
Protection Branch
Division of Radiation Safety
and Safeguards

Enclosure:
NRC Inspection Report

cc w/encl: (See page 2)

11
IE01

cc w/encl:

C. R. Dietz, Manager
Robinson Nuclear Project Department
R. E. Morgan, Plant General Manager
State of South Carolina

bcc w/encl:

NRC Resident Inspector
DRS Technical Assistant
Document Control Desk

RII

RII

MLauer:tj
03/ /89

JPotter
03/ /89