NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201	ETY INSPECTIO	N REPORT AND		S. NUCLEAR REGULATO	RY COMMISSION
LICENSEE/LOCATION INSPECTED: Caribbean Geo-Technology, PSC Paseos Reales #BK-30 Arecibo, PR REPORT NUMBER(S) 2014001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
3. DOCKET NUMBER(S) 4. LICENSE NUMBER		SE NUMBER(S)		5. DATE(S) OF INSPECT	ION
03038677	52-35098-01			June 23, 2014	
LICENSEE:	l			,	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X					
		ement of Correct			
I hereby state that, within 30 days, the corrective actions is made in accordar date when full compliance will be achi	nce with the requireme	ents of 10 CFR 2.201 (corrective steps alread	dy taken, corrective steps w	vhich will be taken,
Title	Prin	ted Name		Signature	Date
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Todd J. Jackson, CHP			/RA/	6/23/14
BRANCH CHIEF	Blake Welling			/RA/	7/23/14
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\WordDocs\Current\Insp Record\R52-35098-01.2014001.591M-Part1.doc					
SUNSI Review Completed By:	/ RA / Too	dd Jackson		X Public x	Non-Sensitive