

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 10814

FILE: _____

FROM: Carolina Power & Light Hartsville, S. C. Jack B. McGirt			DATE OF DOC 9-3-74	DATE REC'D 10-18-74	LTR X	TWX	RPT	OTHER
TO: N.C. Moseley			ORIG 1 signed	CC	OTHER	SENT AEC PDR <u>X</u> SENT LOCAL PDR <u>X</u>		
CLASS	UNCLASS XX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		

DESCRIPTION:

Ltr reporting abnormal occurrence on 8-31-74 in which valve V2-16C motor driven auxiliary feedwater pump discharge valve to "O" steam generator did not open....

ENCLOSURES:

PLANT NAME: H.B. Robinson

FOR ACTION/INFORMATION LMB 10-18-74

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u> AEC PDR OGC, ROOM P-506A MUNTZING/STAFF CASE GIAMBUSSO BOYD MOORE (L) (BWR) DEYOUNG (L) (PWR) SKOVHOLT (L) GOLLER (L) P. COLLINS DENISE REG OPR FILE & REGION (3) MORRIS STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLIMER	<u>DENTON</u> GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> DIGGS (L) GEARIN (L) GOULBOURNE (L) KREUTZER (E) LEE (L) MAIGRET (L) REED (E) SERVICE (L) SHEPPARD (L) SLATER (E) SMITH (L) TEETS (L) WILLIAMS (E) WILSON (L)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD CHAPMAN DUBE w/input E. COUPE D. THOMPSON (2) KLECKER EISENHUT
---	--	--	---	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Hartsville, S.C	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - ASLBP (E/W Bldg, Rm 529)	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - W. PENNINGTON, Rm E-201 GT	1 - G. ULRIKSON, ORNL
1 - ASLB	1 - B&M SWINEBROAD, Rm E-201 GT	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson	1 - CONSULTANTS	1 - R. D. MUELLER, Rm E-201 GT
5 - ACRS	NEWMARK/BLUME/AGBABIAN	
SENT TO TEETS		


CP&L

Regulatory

Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina

September 3, 1974



Robinson File No. 2-0-4-a-1

Mr. Norman C. Moseley, Director
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N.W.
Atlanta, Georgia 30303



Mr. Edison Case, Acting Director
Directorate of Licensing (Office of Regulation)
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Sirs:

In accordance with section 6.6.2 of the Technical Specifications the following abnormal occurrence is reported.

At 1100, August 31, 1974, during hot shutdown conditions, shifting of main feedwater pumps resulted in a normal condition which satisfied the automatic start logic of the motor driven auxiliary feedwater pumps and valves. When this occurred, valve V2-160, motor driven auxiliary feedwater pump discharge valve to "O" steam generator, did not open. The steam driven auxiliary feedwater pump was test operated satisfactorily proving the ability to feed all steam generators in emergency conditions.

This was reported to Mr. Herb Whitener of AEC DRO on August 31, 1974.

Yours very truly,

Jack B. McGirt, Manager
H. B. Robinson SEG Plant

AOT:gg

10814