

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 4731

FILE: 470

FROM: Carolina Power & Light Co. Raleigh, North Carolina Benny J. Furr			DATE OF DOC 5-28-74	DATE REC'D 5-29-74	LTR	MEMO	RPT	OTHER TWX
TO: Norman C. Moseley			ORIG 1	CC	OTHER	SENT AEC PDR <u>XXX</u> SENT LOCAL PDR <u>XXX</u>		
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-261		
	XXX							

DESCRIPTION:

Twx furniinfo re abnormal occurrence discovered 5-27-74 in which the purge fans had been operating at approx. 80% design flow during testing

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: H. B. ROBINSON UNIT #2

FOR ACTION/INFORMATION 5-31-74 GMC

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	ZIEMANN(L) W/ Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
PARR(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	✓PURPLE (L) W/ 7 Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

✓REG FILE	TECH REVIEW	DENTON	LIC ASST	A/T IND
✓AEC PDR	✓HENDRIE	GRIMES		BRAITMAN
✓OGC, ROOM P-506A	SCHROEDER	GAMMILL	DIGGS (L)	SALTZMAN
✓MUNTZING/STAFF	✓MACCARY	KASTNER	GEARIN (L)	B. HURT
✓CASE	✓KNIGHT	BALLARD	GOULBOURNE (L)	<u>PLANS</u>
GIAMBUSSO	✓PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓SHAO		MAIGRET (L)	DUBE w/Input
MOORE (L)(BWR)	✓STELLO	<u>ENVIRO</u>	REED (E)	<u>INFO</u>
DEYOUNG(L)(PWR)	✓HOUSTON	MULLER	SERVICE (L)	C. MILES
SKOVHOLT (L)	✓NOVAK	DICKER	SHEPPARD (L)	✓KLECKER
✓GOLLER(L)	✓ROSS	KNIGHTON	SLATER (E)	✓EISENHUT
P. COLLINS	✓IPPOLITO	YOUNGBLOOD	SMITH (L)	
DENISE	✓TEDESCO	REGAN	✓TEETS (L)	
✓REG OPR	✓LONG	PROJECT LDR	WADE (E)	✓AOR FILE
FILE & REGION(3)	✓LAINAS		WILLIAMS (E)	D. THOMPSON (2)
✓MORRIS	✓BENAROYA	HARLESS	WILSON (L)	
	✓VOLLMER			

EXTERNAL DISTRIBUTION


✓1 - LOCAL PDR <u>HARTVILLE, SC</u>	(1)(2)(10)-NATIONAL LAB'S	1-PDR-SAN/LA/NY
1 - TIC (ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-GERALD LELLOUCHE
1 - NSIC(BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	BROOKHAVEN NAT. LAB
1 - ASLB	1-CONSULTANT'S	1-AGMED(Ruth Gussman)
1 - P. R. DAVIS (AEROJET NUCLEAR)	NEWMARK/BLUME/ACBABIAN	RM-B-127, GT.
✓16 - CYS ACRS <u>HOLDING</u>	1-GERALD ULRICKSON...GRNL	1-RD..MULLER..F-309 GT
Sent to Lic Asst Teets 5-31-74	1-B & M SWINEBROAD, Rm E-201 GT	

CP&L

Carolina Power & Light Company

**H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina**


May 28, 1974



Robinson File No. 2-O-4-a-1

50-261

**Mr. Norman C. Moseley, Director
U. S. Atomic Energy Commission
Directorate of Regulatory Operations
Region II - Suite 818
230 Peachtree Street, N. W.
Atlanta, Georgia 30303**



**Mr. John F. O'Leary
Directorate of Licensing (Office of Regulation)
U. S. Atomic Energy Commission
Washington, D. C. 20545**

Dear Sirs:

In accordance with Section 6.6.2 of the Technical Specification the following abnormal occurrence is reported. Section 3.8.2.c of the Technical Specification requires that the containment vessel purge fan be shown to operate with ~ 10% of design flow if the fan is to be operated while fuel is being moved. On 5-27-74, review of the final test report showed that the purge fans had been operating at approximately 80% of design flow during the test. Operation of the purge fans was discontinued until the problem can be resolved. Fuel handling with the purge fans operating will not be allowed until this limiting condition for fuel handling operation can be met.

This event was reported by telephone to Mr. Herb Whitener on 5-28-74, and a ten day report will follow.

Yours very truly,

**Donny J. Furr, Manager
H. B. Robinson SEG Plant**

BJF:ta

CC: H. B. Beasac

REGULATORY DOCKET FILE COPY

4731