AEC DISTRIBUTION FOR PART 50 DOCKET MAT (TEMPORARY FORM)

CONTROL NO: 5438 FILE: DATE OF DOC DATE REC'D OTHER LTR MEMO RPT Carolina Power & Light Co. Hartsville, S. C. Benny J. Furr 7-13-73 7-10-73 TWX TO: ORIG OTHER SENT AEC PDR Х SENT LOCAL PDR Х John F. O'Leary 1 UNCLASS NO CYS REC'D CLASS PROP INFO INPUT DOCKET NO: XX 1 50 - 261DESCRIPTION: ENCLOSURES: TWX, reporting an abnormal occurrence on 7-10-73, in which the circuit breaker for cooler number two fan tripped...... ACKNOWLEGGED Do Not Remove PLANT NAME: H. B. Robinson Unit No. 2 FOR ACTION/INFORMATION 7-16-73 AB BUTLER(L) SCHWENCER(L) ZIEMANN(L) REGAN(E) W/ Copies W/ Copies W/ Copies W/ Copies STOLZ(L) CLARK(L) DICKER(E) W/ Copies W/ Copies Copies W/ Copies GOLLER(L) VASSALLO(L) KNIGHTON (E) W/ Copies W/ Copies W/ Copies Copies KNIEL(L) SCHEMEL(L) YOUNGBLOOD (E) W/7 Copies W/ Copies W/ Copies W/ Copies INTERNAL DISTRIBUTION REG FILE TECH REVIEW DENTON LIC ASST A/T IND AEC PDR BROWN (E) - HENDRIE GRIMES BRAITMAN DIGGS (L) OGC, ROOM P-506A SCHROEDER GAMMILL SALTZMAN ✓ MACCARY / MUNTZING/STAFF KASTNER GEARIN (L) CASE KNIGHT BALLARD GOULBOURNE (L) **PLANS** GIAMBUSSO > PAWLICKI **SPANGLER** MCDONALD LEE (L) > SHAO BOYD MAIGRET (L) DUBE _ STELLO MOORE (L) (BWR) **ENVIRO** SERVICE (L) HOUSTON SHEPPARD (E) DEYOUNG(L)(PWR) MULLER INFO C. MILES SKOVHOLT (L) NOVAK DICKER SMITH (L) P. COLLINS ROSS TEETS (L) KNIGHTON ✓ IPPOLITO ✓ B. KING(REG OPR E/W YOUNGBLOOD WADE (E) **▼** TEDESCO Bldg, OGE) REG OPR REGAN WILLIAMS (E) FILE & REGION(3) WILSON (L) ✓ LONG PROJECT LDR ✓ LAINAS MORRIS STEELE ✓ BENAROYA **HARLESS** ✓ VOLLMER EXTERNAL DISTRIBUTION 1 - LOCAL PDR Hartville, S. (1)(2)(9)-NATIONAL LAB'S ✓ 1 - DTIE (ABERNATHY) 1-PDR-SAN/LA/NY 1-R.Schoonmaker, OC, GT.D-323 ✓1 - NSIC (BUCHANAN) 1-GERALD LELLOUCHE 1 - ASLB(YORE/SAYRE/ 1-R. CATLIN, E-256-GT BROOKHAVEN NAT. LAB WOODARD/"H" ST. 1-CONSULTANT'S 1-AGMED (WALTER KOESTER

NEWMARK/BLUME/AGBABIAN

S. TEETS ON 7-16-73 1-GERALD ULRIKSON...ORNL

RM-C-427-GT

1-RD MULLER F-309 GT

16 - CYS ACRS HONDENEX SENT TO LIC ASST.

2-055322B191-001 07/10/73



ICS SOTOIPF MLTN SUSPECTED DUPLICATE 2-080887E191 ICS IPMMTZZ CSP 8033321351 MGM TDMT HARTSVILLE S 152 07-10 0340P EST ZIP 20545

Elle Cy.

JOHN F OLEARY DIRECTORATE OF LICENSING USAEC WASHINGTON DC 20545



IN ACCORDANCE WITH SECTION 6.6.2 OF THE TECHNICAL SPECIFICATIONS THE FOLLOWING ABNORMAL OCCURRENCE IS REPORTED AT 0830 ON JULY 10 WHILE ROUTINELY PUTTING CONTAINMENT FOR COOLER NUMBER TWO IN SERVICE. THE CIRCUIT BREAKER FOR THIS FAN TRIPPED. INVESTIGATION REVEALED THAT THE TRIP WAS INITIATED BY INSTANTANEOUSLY OVER OCCURRENCE CAUSED BY THE MISALIGNMENT OF THE INSTANTANEOUSLY CALIBRATION SPRING IN THE OVER CURRENT TRIP DEVICE. THE DEVICE WAS REMOVED, THE SPRING REALIGNED AND THE COOLING UNIT PUT IN SERVICE SATISFACTORILY AT 1007. TO PREVENT THE RECURRENCE OF THIS TRIP, ALL NEWLY INSTALLED TRIP DEVICES ARE BEING VISUALLY INSPECTED FOR PROPER SPRING ALIGNMENT. THIS UNIT HAD OPERATED

SATISFACTORILY FOLLOWING THE INSTALLATION OF THE NEW TRIP DEVICE. THIS WAS REPORTED TO MR HERB WHITTNER IN PERSON ON JULY 10.

BENNY J FURR MANAGER H B ROBINSON SEG PLANT PO BOX 790 HARTSVILLE SC 29550

2041 EST

MGMWSHB WSH

