BoA 22/118

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS) DISTRIBUTION FOR INCOMING MATERIAL 50~261

REC: VOLGENAU E

ORG: FURR B J

MRC

SUBJECT:

4.5

CAROLINA PWR & LIGHT

DOCDATE: 09/15/78 DATE RCVD: 09/21/78

DOCTYPE: LETTER

NOTARIZED: NO

COPIES RECEIVED

LTR 1 ENCL 1

FORWARDING SUBJECT FACILITY"S MONTHLY OPERATING REPT FOR THE MONTH OF AUGUST,

1978.

PLANT NAME: H B ROBINSON - UNIT 2

REVIEWER INITIAL: X.IM DISTRIBUTOR INITIAL: N

\*\*\*\*\*\*\*\*\* DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS \*\*\*\*\*\*\*\*\*\*\*\*

ANNUAL, SEMI-ANNUAL & MONTHLY OPERATING RPTS (OL STAGE) (DISTRIBUTION CODE ACCR)

FOR ACTION:

BR CHIEF ORB#1 BC\*\*W/6 ENCL

INTERNAL:

REG FILERRAVENCE I & EXAMPLE ENCL HANAUER\*\*W/ENCL

AD FOR SYS & PROJ\*\*W/ENCL REACTOR SAFETY BR\*\*W/ENCL

EEB\*\*W/ENCL

EFFLUENT TREAT SYS\*\*W/ENCL

NRC PDR\*\*W/ENCL MIPC\*\*W/2 ENCL

DIRECTOR DOR\*\*W/FNCL ENGINEERING BR\*\*W/ENCL PLANT SYSTEMS BR\*\*W/ENCL CORE PERFORMANCE BR\*\*W/ENCL

EXTERNAL:

LPDR18

HARTSVILLE, SC\*\*W/ENCL

NATL LAB ANL\*\*W/ENCL

TERA\*\*W/ENCL NSIC\*\*W/ENCL

BROOKHAVEN\*\*W/ENCL ACRS CAT E\*\*W/16 ENCL

DISTRIBUTION: SIZE: 1P+5P

LTR 43

ENCL 43

CONTROL NBR:

\*\*\*\*

780880329

THE END

### \_ \_ \_ \_ \_

September 15, 1978

FILE: NG-3513(R)

SERIAL: GD-78-2464

Mr. Ernst Volgenau, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2

DOCKET NO. 50-261

LICENSE NO. DPR-23

MONTHLY OPERATIONS REPORT

Dear Mr. Volgenau:

In accordance with Technical Specification 6.9.1.c for the H. B. Robinson Steam Electric Plant, Unit No. 2, Carolina Power & Light Company herewith submits the report of operating statistics and shutdown experience for the month of August, 1978.

Yours very truly,

B. J. Furr Manager

Generation Department

DCS:1k

Enclosure

cc: Messrs. R. A. Hartfield J. P. O'Reilly

780880329

## **OPERATING DATA REPORT**

OPERATING STATUS		·	
1 Hait Name: H B Robinson Two	•	Notes	
700001 0000 /700001 0	2400		
2200	2400		•
3. Licensed Thermal Power (MWI):			
4. Nameplate Rating (Gross MWe): 739			
5. Design Electrical Rating (Net MWe): 700	700		
6. Maximum Dependable Capacity (Gross MWe): .	700 665		
7. Maximum Dependable Capacity (Net MWe):			
8. If Changes Occur in Capacity Ratings (Items Nur NONE	nber 3 Through 7) Sin	ce Last Report, Give Ro	easons:
9. Power Level To Which Restricted, If Any (Net M	IWe): NONE		
0. Reasons For Restrictions, If Any: NONE			
o. Reasons to resimenous, in they			
	This Month	Yrto-Date	Cumulative
H. Hanna In Deporting Ported	744	5831	65,693
1. Hours In Reporting Period  2. Number Of Hours Reactor Was Critical	740.43	3890.39	51,072.5]
•	3.57	186.51	611.56
3. Reactor Reserve Shutdown Hours	739.30	3574.71	49,780.58
4. Hours Generator On-Line	0	0	0
5. Unit Reserve Shutdown Hours	1,607,654	7,460,376	101,727,872
6. Gross Thermal Energy Generated (MWH) 7. Gross Electrical Energy Generated (MWH)	494,024	2,332,190	32,837,493
	469,022	2,196,576	31,116,565
8. Net Electrical Energy Generated (MWH)	99.37	61.31	75.78
9. Unit Service Factor	99.37	61.31	75.78
20. Unit Availability Factor	94.80	56.65	71.23
21. Unit Capacity Factor (Using MDC Net)	90.06	53.82	67.67
22. Unit Capacity Factor (Using DER Net)	.63	8.10	14.44
23. Unit Forced Outage Rate 24. Shutdowns Scheduled Over Next 6 Months (Typ	e, Date, and Duration	<del></del>	
· NONE			
25. If Shut Down At End Of Report Period, Estimat	ed Date of Startup: _	ON LINE	
26. Units In Test Status (Prior to Commercial Opera	·	Forecast	Achieved
INITIAL CRITICALITY	•		
INITIAL ELECTRICITY			
COMMERCIAL OPERATION			

#### UNIT SHUTDOWNS AND POWER REDUCTIONS

DPR-23 DOCKET NO. HB Robinson Two UNIT NAME 780906 DATE M. L. Watford **COMPLETED BY** 803-332-1351 TELEPHONE

REPORT MONTH August

No.	Date	Type	Duration (Hours)	Reason-	Method of Shutting Down Reactor <sup>3</sup>	Licensee Event Report #	System Code4	Component Code 5	Cause & Corrective Action to Prevent Recurrence
09-01	780801	F	4.70	A	3	-	СС		Loose screw in S.G. Level (Pen 3) circuitry caused high level alarm which caused the FWRV to go full open.
09-02	780820	S	-	В	4	<del>-</del>	НВ		Power reduction to inspect condenser for possible tube leaks.
			-			· ::			
	•				-				
					·				

F: Forded S: Scheduled

A-Equipment Failure (Explain) B-Maintenance of Test

C-Refueling
D-Regulatory Restriction
F-Operator Training & License Examination
F-Administrative

G-Operational Error (Explain) H-Other (Explain)

(9/77)

Method: 1-Manual

2-Manual Scram.

3-Automatic Scram.

4-Other (Explain)

Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

Exhibit 1 - Same Source

# AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO.	DPR-23				
UNIT	H B Robinson Two				
DATE	780906				

COMPLETED BY M. L. Watford
TELEPHONE 803-332-1351

	•		•
MONT	rh August		
DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
1	470	17	. 642
2	640	18	637
3	644	. 19	631
4	644	20	492
5	647	21	639
6	628	22	641
7	649	23	639
8	650	24	639
9	645	25	640
10	648	26	640
11	648	. 27	622
12	647	28	638
13	631 /	29	640
14	644	. 30	641
15	644	31	639
16	644		•

## **INSTRUCTIONS**

On this format, list the average daily unit power level in MWe-Net for each day in the reporting month. Compute to the nearest whole megawatt.

EQUIPMENT EFFECT ON SAFE		MALFUNCTION		
	OPERATION	CAUSE	RESULTS	CORRECTIVE/PREVENTIVE ACTION
Engine Driven Fire Pp	none	pressure switch misadjustment	starts in auto at bottom of band	switch adjusted
"A" Diesel	none	outboard air start solenoid leaking	leaking air	solenoid replaced
Engine Driven Fire Pp	none	depleted batteries	-	replaced batteries
Service Water Valve V6-12D	none	binding limit switch	closed light would	light switch replaced
Comparator model #4111082-001	none	faulty integrated circuit (A-3)	excessive setpoint drift	circuit (A-3) replaced
Heat Trace Recorder #1	none	defective contact brush assembly	erratic readings	renewed contact brush assembly
"C" Charging Pp	none	bad discharge valves	would not maintain PZR. level with 60 gpm orifice	valves replaced
"C" Charging Pp	none	safety valve valve disc cut	leaking at seat	valve disc replaced
CVC-113B	none	ruptured diaphram	slow operation ,	diaphram replaced
Spent Fuel Cask Vent Valve	none	worn handwheel	unsatisfactory operation	handwheel fabricated and replaced
"B" Boric Acid Transfer	none	defective front bearing housing and impeller	noisy while running	rebuilt pump
"A" Boric Acid Evap. Feed Tank Pp.	- none	inefficient operation	low discharge pres.	pump rebuilt
"C" Main FW_Regulator Valve	none	worn packing	packing leak	packing gland tightened
Valve RHR-HCV-142	none	worn packing	high:stem leakage	renewed packing
HVH-2	none	leaking tubes	leaking fan cooler	tubes soldered and/or plugged
WD1786 RCDT Vent Valve	none	bad control relay	blows fuses	relay replaced

EQUIPMENT	EFFECT ON SAFE	MALFUNCTION	CORRECTIVE/PREVENTIVE ACTION	
OPERATION		CAUSE		
Spent Fuel Pit Crane	none	fuel element hoist upper limit switch out of alignment	limited travel	limit switch readjusted
TR 410	none	faulty floating potentiometer circuit faulty	reading 100°F high	circuit replaced
ΔT Protection	none	loop 3 AT protection out of calibration	indicating high	ΔT protection calibrated
NIS	none	out of calibration	does not agree with calorimetric	NIS calibrated
		٠.	·	
				·