

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Med-Share Incorporated
26222 Telegraph Road
Southfield, MI 48034

REPORT NUMBER(S) 14-001

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-31441

4. LICENSE NUMBER(S)

21-26098-01

5. DATE(S) OF INSPECTION

July 28-29, 2014

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| TITLE | PRINTED NAME | SIGNATURE | DATE |
|---------------------------|--------------------------------------|--|---------|
| LICENSEE'S REPRESENTATIVE | | | |
| NRC INSPECTOR | Deborah A. Piskura, Health Physicist |  | 7/29/14 |
| BRANCH CHIEF | Aaron T. McCraw, Chief, MIB |  | 8/22/14 |

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Med-Share Incorporated
26222 Telegraph Road
Southfield, MI 48034

REPORT NUMBER(S) 14-001

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-31441

4. LICENSE NUMBER(S)

21-26098-01

5. DATE(S) OF INSPECTION

July 28-28, 2014

6. INSPECTION PROCEDURES USED

87130

7. INSPECTION FOCUS AREAS

03.01- 03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)

02220

2. PRIORITY

3

3. LICENSEE CONTACT

Pamela Bradford, CNMT, RSO

4. TELEPHONE NUMBER

(248) 827-7200

☒ Main Office Inspection Next Inspection Date: July 2017

☒ Field Office Inspection 22116 Telegraph Road, Southfield, MI

☒ Temporary Job Site Inspection 32320 Michigan Ave., Wayne, MI

PROGRAM SCOPE

This was routine inspection of a mobile nuclear medicine service provider authorized to use licensed material permitted by Sections 35.100 and 35.200 for imaging procedures. The licensee performed a full spectrum of diagnostic studies with the majority of cases involving cardiac imaging (typically 150 cases per month). The licensee performed studies on Fridays at its Greenfield Road clinic and operated a scan-in-van mobile service utilizing 3-4 coaches in in State of Michigan. Imaging studies were performed daily either in the van or within the clients' facilities. The nuclear medicine group was staffed with 6 PRN technologists. The licensee received unit doses from a licensed radiopharmacy. The licensee retained the services of a consulting physicist who audited the radiation safety program on a quarterly basis (last 6/17/2014).

This inspection consisted of interviews with licensee personnel, independent measurements, and a review of select records. The inspection included observations of licensed activities at a temporary job site. The inspector observed licensee personnel maintain security of its RAM, utilize personnel monitoring, and administer unit dosages for cardiac imaging.

No violations of NRC requirements were identified during this inspection.