

Bo. 2

*06-14001-01
030-03850*

*06-31456-01
030-38495*

Licensing Assistance Team
Division of Nuclear Materials Safety
U.S. Nuclear Regulatory Commission, Region I
2100 Renaissance Boulevard, Suite 100
King of Prussia, PA 19406-2713

REC'D 09/23/14 AM 07:03

Sept. 18, 2014

To whom it may concern,

We intend to transfer operations of our specifically licensed devices back to the general license that ABB Inc. supplied with the equipment originally. Nothing has changed with the installation or use of the devices and they have been inspected by ABB for radiological safety continuously throughout our ownership as per NRC requirements.

This affects two specific licenses for devices operated by us. License #06-14001-01 for equipment owned by Ahlstrom Nonwovens LLC and license #06-31456-01 for equipment owned by Suominem Corporation.


I am currently the RSO for both licenses and will be retiring Oct. 31, 2014. Ahlstrom no longer wishes to hold specific licenses for these devices.

We have talked to ABB and their radiological personnel about this. Our intention is to have ABB perform a normal radiation safety inspection to verify that everything is in order to allow us to operate under the general license. They will also affix the appropriate radiation label for generally licensed devices on each device. We will then forward the safety test results to the NRC along with a request to surrender our specific licenses and proceed with operating under the conditions of the general license.

Going forward, ABB will provide maintenance and radiological safety inspections on this equipment per a service contract agreement with us.

Please provide any necessary guidance on this.

Timothy Daly, RSO



T: 860-654-8560

F: 860-654-8569

Email: tim.daly@ahlstrom.com

584972/584974
NRC/REGNI MATERIALS-002

This is to acknowledge the receipt of your letter/application dated

09/18/2014, and to inform you that the initial processing which includes an administrative review has been performed.

There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 584972
584974.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.