NRC FORM 591M PART 1 (4-2008) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
	SPECTION REPORT AND			7N
1. LICENSEE/LOCATION INSPECTED:		2. NRC/REGIONAL OFFICE		
Weatherford International, LLC & Subsidiaries I Affiliate Companies 7504 Benbrook Parkway Benbrook, Texas 76126 Location: Airport Way, Pouch 340120, Deadhorse, Alaska		U.S. Nuclear Regulatory Commission Region IV 1600 East Lamar Boulevard Arlington, Texas 76011-4511		
REPORT NO: 030-30118/2014-002				
3. DOCKET NUMBER	4. LICENSE NUMBER		5. DATES OF	
030-30118	42-26891-01		August 12	2-29, 2014
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X				
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date				
LICENSEE'S REPRESENTATIVE		Λ .		-
NRC INSPECTOR R. Rick Muñ	ioz .	MCY.		08/29/2014
BRANCH CHIEF G. Michael Va	14-101	Varge) (",	17/2014
NRC FORM 591M PART 1 (Rev. by RIV 3/09) Non-Public Sensitive — Se	s:\DNM\$\!\NMIB\BRANCH FORM\$\!591\vert curity-Related		Public	X Non-Sensitive