



U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

DCS-NRC-000378
13 November 2014

Subject: Docket Number 070-03098
Shaw AREVA MOX Services
Mixed Oxide Fuel Fabrication Facility
Closure of Interim Report Notification: Deformed Bar Anchors


Reference: 1. Letter from K. Trice to U.S. NRC Document Control Desk, DCS-NRC-000374,
"Part 21 60-Day Interim Report Notification: Nelson Deformed Bars," dated
May 28, 2014

2. Letter from K. Trice to U.S. NRC Document Control Desk, DCS-NRC-000376,
"Updated Interim Report Notification: Nelson Deformed Bars," dated
August 26, 2014

CB&I AREVA MOX Services, LLC (MOX Services), submitted an interim report (Reference 1) and an updated interim report (Reference 2) regarding Nelson Deformed Bars. Evaluation of the condition identified in the interim reports has been completed. This condition has been determined to not be reportable in accordance with 10 CFR Part 21.

If you have any questions, please feel free to contact me at (803) 442-6485 or Dealis Gwyn, Licensing Manager at (803) 819-2780.

Sincerely,



David Del Vecchio, President

Document Control Desk
U.S. Nuclear Regulatory Commission
DCS-NRC-000378
13 November 2014
Page 2 of 2

cc :

Scott Cannon, NNSA/SRS
Mosi Dayani, NNSA/SRS
William Gloersen, USNRC/RII
Mark Gober, MOX Services
Dealis Gwyn, MOX Services
Chad Huffman, USNRC/SRS
Kevin Morrissey, USNRC/HQ
Gilles Rousseau, MOX Services
Deborah Seymour, USNRC/RII
Donald Silverman, ML&B
David Tiktinsky, USNRC/HQ
Rodney Whitley, MOX Services
Paul Whittingham, MOX Services
Bryan Wilkes, MOX Services
Lauren Wylie, MOX Services
EDMS: Corresp\\Outgoing\NRC\2014 NRC