

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: JanX Integrity Group 8550 East Michigan Avenue Parma, MI 49269 REPORT NUMBER(S) 2014-002	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S) 030-11772	4. LICENSE NUMBER(S) 21-16560-01	5. DATE(S) OF INSPECTION December 4, 2014

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
 (Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Ryan Craffey		12/4/14
BRANCH CHIEF	Aaron McCraw		12/9/14

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: JanX Integrity Group 8550 East Michigan Avenue Parma, MI 49269 REPORT NUMBER(S) 2014-002	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 030-11772	4. LICENSE NUMBER(S) 21-16560-01	5. DATE(S) OF INSPECTION December 4, 2014
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED 87121	7. INSPECTION FOCUS AREAS All
--	--------------------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT William Reeve - RSO	4. TELEPHONE NUMBER (517) 531-8210
---------------------------------	----------------------	--	---

Main Office Inspection Next Inspection Date: No change

Field Office Inspection _____

Temporary Job Site Inspection Saginaw and Wayne, MI

PROGRAM SCOPE

This was a routine field inspection of a large non-destructive testing company authorized to use radioactive material for industrial radiography at numerous field stations and at temporary job sites throughout NRC jurisdiction. At the time of the inspection, the licensee scheduled work and maintained equipment for its Michigan operations primarily from a field station in Mount Pleasant.

PERFORMANCE OBSERVATIONS

The inspector observed the conduct of radiographic operations at two temporary job sites: 778 Bridgeview South, Saginaw, Michigan and at the intersection of Hannan and Ecorse Roads in Wayne, Michigan. The inspector noted the satisfactory use of restricted area barriers during these operations, as confirmed by independent surveys. Through discussions of such topics as barrier calculation, equipment maintenance and emergency response, the inspector found that the radiographers and their assistants were knowledgeable of radiation protection principles and licensee procedures, and their dosimetry and survey instruments were calibrated and operable.

The inspector reviewed a selection of available safety-related records, including utilization logs, shipping papers, and the licensee's most recent revision to its operating and emergency procedures.

No violations of NRC safety requirements were identified as a result of this inspection. The inspector conducted a telephonic exit meeting with the licensee on December 8, 2014.