

71-9269

**BAKER TESTING SERVICES, INC.**

NONDESTRUCTIVE EXAMINATION

METALLURGY AND FAILURE ANALYSIS

www.bakertesting.com

22 Reservoir Park Drive, Unit 1  
Rockland, MA 02370

(781) 871-4458

(781) 871-0123 (FAX)

1-6-15

Re: Notification Requirement for Type B Package USA/9269/B(U)-96

Ms. Michele Sampson, Chief  
Spent Fuel Licensing Branch  
U.S. Nuclear Regulatory Commission  
Office of Nuclear Material Safety and Safeguards  
Division of Spent Fuel Management  
Mail Stop 3WFN-14A44  
Washington, D.C. 20555-0001

As our supplier of radiography sources, QSA Global, Inc. has informed Baker Testing Services, Inc., that minor package configuration discrepancies were identified on their Model 650L Type B Package (Certificate of Conformance USA/9269/B(U)-96).


In September 2010, QSA Global, Inc. added more stringent material requirements for the top and bottom plates and some hardware components on the 650L. However, all of the descriptive drawings were not documented accurately. A review by QSA Global, Inc. in December 2014 revealed the discrepancy as reported to your office on December 8, 2014.

Because we have made shipments of this type B package between September 14, 2010 and December 8, 2014 we are making this report to you under 10 CFR 71.95(a)(3).


We understand that there is no safety impact, and the issues identified have not contributed to any incidents or failures related to the safe use of the 650L during transport but that these discrepancies involve QSA Global, Inc. documentation issues.

We are aware that Revision 8 to the Certificate of Conformance USA/9269/B(U)-96 was issued on December 9, 2014 which allows continued use of the 650L. QSA Global, Inc. is taking full responsibility for corrective actions. No further action will be taken by Baker Testing Services, Inc. at this time.

Sincerely,

  
James W. Rowe  
President

Assistant Radiation Safety Officer



N145501