NRC FORM 591M PA (4-2008) 10 CFR 2.201			U.S. NUCLEAR REGULATORY COMMISSION		
4 1105110554.0047					<del></del>
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE		
Nuclear Diagnosis, LLC P.O. Box 189 Spearfish, South Dakota 57783 Location: 3103 East Fairground Loop, Suite 4, Spearfish, SD			U.S. Nuclear Regulatory Commission - Region IV 1600 East Lamar Boulevard Arlington, Texas 76011-4511		
REPORT NO: 030	-35934/2013-001				
3. DOCKET NUMBER	4.	LICENSE NUMBER		5. DATES OF IN	SPECTION
030-35934		40-27719-01		July 29-3	1, 2013
LICENSEE:	<u> </u>	<del></del>		<u> </u>	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspection. The inspection findings are as follows:  X					
	Licensee's St	atement of Corrective	Actions for Iter	n 4, above.	
corrective actions is ma	in 30 days, the actions descr de in accordance with the re ce will be achieved). I under Printed Name	ibed by me to the inspector quirements of 10 CFR 2.201	will be taken to correc (corrective steps alre	t the violations iden	ve steps which will be taken.
LICENSEE'S REPRESENTATIVE			N = 11		
NRC INSPECTOR	R. Rick Muñoz	)	LD Mui		07/31/2013
BRANCH CHIEF	G. Michael Vasque	ez Am	(aug) (	) 1/2	15
NON-Public	Sensitive – Securit	y-Related		Public X	FORMS\Part1 Publicly Available.doc  Non-Sensitive