



ECS MID-ATLANTIC, LLC

"Setting the Standard for Service"

Geotechnical • Construction Materials • Environmental • Facilities

02/25/2015

NRC

Division of Nuclear Material Safety

Region 1

Attention: Material Licensing

475 Allendale Road

King of Prussia, PA 9406

Br. 2

Reference: Amendment Request for License # 45-24974-01 *1030-30462*

Due to the finishing of the 11th street project in Washington DC SE, the site construction offices will close. Therefore, we would like to decommission the semi-permanent storage facility from our license. Enclosed are the leak test results of the storage facility.

If you have any questions regarding the contents of this letter, or if there is need for further information, please contact us.

Sincerely,

Karl Higgins, III, PE

Vice President

586183
NMSS/RGNI MATERIALS-002

REC'D IN LAI *02/26/2015*



North East Technical Services, Inc.
75 Alleron Ct, Suite 4
Westminster, MD 21157
Ph: 410.751.5090 Fax: 410.751.5091

ECS Mid-Atlantic, LLC - Chantilly
14026 Thunderbolt Pl, Suite 100
Chantilly, VA 20151
ATTN: Mohamed Elbulok

*Shipping Address: 14026 Thunderbolt Pl, Suite 100
Chantilly, VA 20151*

LEAK TEST CERTIFICATE

MD Materials License # MD-13-020-01

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removeable contamination.

Gauge Model	11 Street Bridge Gauge S/N	Storage Wall 1	Leak Test Date	11/25/2014
	Source	Reading in microCuries		
		0.00005059		
		0.00000		

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source. The source(s) tested above may remain in use.

Reviewed by: Douglas Sims

Date: NOV 25 2014



North East Technical Services, Inc.
75 Aileron Ct., Suite 4
Westminster, MD 21157
Ph: 410.751.5090 Fax: 410.751.5091

ECS Mid-Atlantic, LLC - Chantilly
14026 Thunderbolt Pl., Suite 100
Chantilly, VA 20151
ATTN: Mohamed Elbulok

Shipping Address: 14026 Thunderbolt Pl., Suite 100
Chantilly, VA 20151

LEAK TEST CERTIFICATE

MD Materials License # MD-13-020-01

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removeable contamination.

Gauge Model	11 Street Bridge Gauge S/N	Storage Wall 2	Leak Test Date	11/25/2014
Source	Reading in microCuries			
	0.00005059			
	0.00000			

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source. The source(s) tested above may remain in use.

Reviewed by: Douglas Sims

Date: NOV 25 2014



North East Technical Services, Inc.
75 Aileron Ct., Suite 4
Westminster, MD 21157
Ph: 410.751.5090 Fax: 410.751.5091

ECS Mid-Atlantic, LLC - Chantilly
14026 Thunderbolt Pl., Suite 100
Chantilly, VA 20151
ATTN: Mohamed Elbulok

Shipping Address: 14026 Thunderbolt Pl., Suite 100
Chantilly, VA 20151

LEAK TEST CERTIFICATE

MD Materials License # MD-13-020-01

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removeable contamination.

Gauge Model	11 Street Bridge Gauge S/N	Storage Wall 3	Leak Test Date	11/25/2014
Source	Reading in microCuries			
	0.00005059			
	0.00000			

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source. The source(s) tested above may remain in use.

Reviewed by: *Doyle Sims*

Date: NOV 25 2014



*North East Technical Services, Inc.
75 Aileron Ct., Suite 4
Westminster, MD 21157
Ph: 410.751.5090 Fax: 410.751.5091*

*ECS Mid-Atlantic, LLC - Chantilly
14026 Thunderbolt Pl., Suite 100
Chantilly, VA 20151
ATTN: Mohamed Elbulok*

*Shipping Address: 14026 Thunderbolt Pl., Suite 100
Chantilly, VA 20151*

LEAK TEST CERTIFICATE

MD Materials License # MD-13-020-01

This certifies that leak test analysis was conducted on the sample with the following information. The results shown below accurately represent the level of removeable contamination.

Gauge Model	11 Street Bridge Gauge S/N	Storage Wall 4	Leak Test Date	11/25/2014
	Source		Reading in microCuries	
			0.00005059	
			0.00000	

Note: 0.005 microCuries (185 Bq) or greater is considered a leaking source. The source(s) tested above may remain in use.

Reviewed by: *Douglas Sims*

Date: NOV 25 2014

This is to acknowledge the receipt of your letter application dated

02/25/2015, and to inform you that the initial processing which includes an administrative review has been performed.

45-24974-01 (Amendment)
 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 586183.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.