

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  JanX Integrity Group 8550 East Michigan Avenue, Parma, MI 49269  Locations inspected: Clarksburg and West Union, WV  REPORT NUMBER(S) 2014-003		2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352	
3. DOCKET NUMBER(S)  030-11772	4. LICENSE NUMBER(S)  21-16560-01	5. DATE(S) OF INSPECTION  05/07/14, with in-office review through 03/12/15	

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Michael Reichard (Region I)	<i>Def. Coffey FOR MR</i>	3/13/15
BRANCH CHIEF	Aaron McCraw	<i>[Signature]</i>	3/20/15

**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  JanX Integrity Group 8550 East Michigan Avenue, Parma, MI 49269  Locations inspected: Clarksburg and West Union, WV  REPORT NUMBER(S) 2014-003	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S)  030-11772	4. LICENSE NUMBER(S)  21-16560-01	5. DATE(S) OF INSPECTION  05/07/14, with in-office review through 03/12/15
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED  87121	7. INSPECTION FOCUS AREAS  All
--	--------------------------------------

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)  03320	2. PRIORITY  1	3. LICENSEE CONTACT  William Reeve, RSO	4. TELEPHONE NUMBER  (517) 531-8210
---------------------------------	----------------------	---	---

Main Office Inspection                      Next Inspection Date:                      No change

Field Office Inspection    Clarksburg and West Union, WV

Temporary Job Site Inspection    Route 50 and Stillwell Road, Walker, WV

**PROGRAM SCOPE**

This was an unannounced routine inspection, the scope of which was limited to the activities conducted at field offices and temporary job sites in West Virginia. The license is a large non-destructive testing company authorized to use radioactive material for industrial radiography at numerous field stations and at temporary job sites throughout NRC jurisdiction. At the time of the inspection, the West Union location on the license did not possess any material, and had not for some time. The Clarksburg location was active, however, and as such was the focus of this inspection.

**PERFORMANCE OBSERVATIONS**

The inspector interviewed two authorized users at the temporary job site and found them to be knowledgeable of the licensee's Operating and Emergency Procedures. The inspector observed the authorized users' survey meters, dosimeters, and alarming ratemeters, and found that they were in calibration and working properly. The inspector observed the authorized users perform radiography in accordance with safe practices. The inspector performed surveys in the unrestricted areas during the conduct of radiographic operations at the temporary job site; all measurements were below NRC regulatory limits. The inspector found the boundaries to be well controlled and posted.

The inspector observed that the authorized users possessed current versions of various documents, including leak test records, calibration records, dosimetry records, training certificates, and radiographer audits. The inspector confirmed with the Radiation Safety Officer that all other records were stored at their Michigan location.

No violations of NRC safety requirements were identified during this inspection.