

OCONEE NUCLEAR STATION

MONTHLY OPERATING STATUS REPORT

June 1994

1. Personnel Exposure -

The total station liquid release for June has been compared with the Technical Specifications maximum annual dose commitment and was less than 10 percent of this limit.

The total station gaseous release for June has been compared with the Technical Specifications maximum annual dose commitment and was less than 10 percent of this limit.

DOCKET: 50-269

UNIT: Oconee 1

Date: 07/15/94

\* REVISION 1

### NARRATIVE SUMMARY

MONTH: June 1994

Oconee Unit 1 began the month of June in end-of-cycle 15 refueling outage. The unit was in the refueling outage until 06/27 at 0204. The outage was 59.13 days and was scheduled for 49 days. The refueling outage was extended; 6 days due to reactor coolant pump maintenance; 1 day due to axial power shaping rods; 2 days due to secondary plant maintenance and 1.13 days due to start-up delays. The unit held at 15% power until 06/27 at 1159 to conduct the turbine overspeed trip test. The unit was placed on-line at 1447 and began power escalation. The unit held at 23% power on 06/27 from 1615 to 2100 and also, at 30% power from 2332 to 06/28 at 0156 for calibration of nuclear instrumentation. The unit held at 71% power on 06/28 at 1855 to 06/29 at 0520 and also, at 73% power from 0555 to 1420 for power escalation testing. The unit returned to 100% power on 06/30 at 0245 and operated at or near 100% full power the remainder of the month.

Prepared by: R. A. Williams  
Telephone: (704)-382-5346

\* REVISION 1

PAGE 1 OF 2

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH June 1994

DOCKET NO. 50-269  
 UNIT NAME OCONEE 1  
 DATE 07/15/94  
 COMPLETED BY R. A. Williams  
 TELEPHONE (704)-382-5346

(1) NO.	DATE	TYPE	DURATION HOURS	(2) REASON	(3) METHOD OF SHUT DOWN R/X	LICENSE EVENT REPORT NO.	(4) SYS- TEM CODE	(5) COMPONENT CODE	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
2	94- 6- 1	S	383.00	C	--		RC	FUELXX	END-OF-CYCLE 15 REFUELING OUTAGE
3	94- 6-16	S	144.00	B	--		CB	PUMPXX	6 DAY OUTAGE EXTENSION DUE TO REACTOR COOLANT PUMP MAINTENANCE
4	94- 6-22	S	24.00	A	--		RB	CONROD	1 DAY OUTAGE EXTENSION DUE TO AXIAL POWER SHAPING RODS COUPLING
5	94- 6-23	S	48.00	B	--		XX	XXXXXX	2 DAY OUTAGE DUE TO SECONDARY PLANT MAINTENANCE
6	94- 6-25	S	27.07	B	--		RC	XXXXXX	1.13 DAY OUTAGE EXTENSION DUE TO START-UP DELAYS
7-P	94- 6-27	S	--	B	--		HA	TURBIN	HOLDING AT 15% POWER FOR TURBINE OVERSPEED TRIP TEST
7	94- 6-27	S	2.80	B	--		HA	TURBIN	TURBINE OVERSPEED TRIP TEST

- (1)  
 F Forced  
 S Scheduled

- (2) Reason:  
 A-Equipment Failure (Explain)  
 B-Maintenance or test  
 C-Refueling  
 D-Regulatory Restriction  
 E-Operator Training & License Examination  
 F-Administrative  
 G-Operator Error (Explain)  
 H-Other (Explain)

- (3) Method:  
 1-Manual  
 2-Manual Scram  
 3-Automatic Scram  
 4-Other (Explain)

- (4) Exhibit G - Instructions for Preparation of Data Entry Sheets For Licensee Event Report (LER) File (NUREG-0161)

- (5) Exhibit I - Same Source

\* REVISION 1

PAGE 2 OF 2

UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH June 1994

DOCKET NO. 50-269  
 UNIT NAME OCONEE 1  
 DATE 07/15/94  
 COMPLETED BY R. A. Williams  
 TELEPHONE (704)-382-5346

NO.	DATE	(1) TYPE	DURATION HOURS	(2) REASON	(3) METHOD OF SHUT DOWN R/X	LICENSE EVENT REPORT NO.	(4) SYS- TEM CODE	(5) COMPONENT CODE	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
8-P	94- 6-27	S	--	B	--		IA	INSTRU	NUCLEAR INSTRUMENTATION CALIBRATION
9-P	94- 6-27	S	--	B	--		IA	INSTRU	NUCLEAR INSTRUMENTATION CALIBRATION
10-P	94- 6-28	S	--	B	--		RB	INSTRU	POWER ESCALATION TESTING
11-P	94- 6-29	S	--	B	--		RB	INSTRU	POWER ESCALATION TESTING

(1)  
 F Forced  
 S Scheduled

(2)  
 Reason:  
 A-Equipment Failure (Explain)  
 B-Maintenance or test  
 C-Refueling  
 D-Regulatory Restriction  
 E-Operator Training & License Examination  
 F-Administrative  
 G-Operator Error (Explain)  
 H-Other (Explain)

(3)  
 Method:  
 1-Manual  
 2-Manual Scram  
 3-Automatic Scram  
 4-Other (Explain)

(4)  
 Exhibit G - Instructions  
 for Preparation of Data  
 Entry Sheets For Licensee  
 Event Report (LER)  
 File (NUREG-0161)

(5)  
 Exhibit I - Same Source