

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9709230106 DOC.DATE: 97/09/16 NOTARIZED: NO DOCKET #  
FACIL:50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269  
50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270  
50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH.NAME AUTHOR AFFILIATION  
MCCOLLUM,W.R. Duke Power Co.  
RECIP.NAME RECIPIENT AFFILIATION  
Document Control Branch (Document Control Desk)

SUBJECT: Responds to NRC 970902 RAI re violations noted in insp repts  
50-269/97-05,50-270/97-05 & 50-287/97-05 respectively.  
Corrective actions:detailed process control issued for  
specific & must document uncompleted specified insps.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3  
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 PD	1 1	LABARGE,D	1 1
INTERNAL:	ACRS	2 2	AEOD/SPD/RAB	1 1
	AEOD/TTC	1 1	DEDRO	1 1
	FILE CENTER	1 1	NRR/DISP/PIPB	1 1
	NRR/DRCH/HHFB	1 1	NRR/DRPM/PECB	1 1
	NRR/DRPM/PERB	1 1	NUDOCS-ABSTRACT	1 1
	OE DIR	1 1	OGC/HDS2	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LITCO BRYCE,J H	1 1	NOAC	1 1
	NRC PDR	1 1	NUDOCS FULLTEXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:  
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS  
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL 20

C  
A  
T  
E  
G  
O  
R  
Y  
1  
D  
O  
C  
U  
M  
E  
N  
T



**Duke Power Company**  
A Duke Energy Company  
Oconee Nuclear Site  
P.O. Box 1439  
Seneca, SC 29679

W. R. McCollum, Jr.  
Vice President

(864) 885-3107 OFFICE  
(864) 885-3564 FAX

September 16, 1997

U.S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

Subject: Oconee Nuclear Site  
Docket Nos. 50-269, -270, -287  
Inspection Report 50-269, -270, -287/97-05  
Reply to Notice of Violation

Gentlemen:

On September 2, 1997, the NRC requested additional information related to Violation 97-05-03 (Example 2).

Duke Power submitted its response to this violation on August 18, 1997. This additional information documents the corrective actions that are in place for the Unit 1 Refueling (1EOC17). These actions address the root cause to prevent further violations.

Pursuant to the provisions of 10 CFR 2.201, the attachment provides written response to the subject violation as identified in the subject Inspection Report.

Very truly yours,

W. R. McCollum, Jr.  
Site Vice President  
Oconee Nuclear Station

IED 11/1

9709230106 970916  
PDR ADOCK 05000269  
G PDR

000081



NRC Document Control Desk  
September 16, 1997  
Page 2

cc: Mr. L. A. Reyes, Regional Administrator  
U. S. Nuclear Regulatory Commission, Region II

Mr. D. E. LaBarge, Project Manager  
Office of Nuclear Reactor Regulation

Mr. M. A. Scott  
Senior Resident Inspector  
Oconee Nuclear Site

Attachment 1  
Supplemental Information to Notice of Violation  
Violation 97-05-03

In addition to the long-term corrective actions, the following corrective steps are in place for the upcoming Unit 1 refueling outage (1EOC17):

- a) In addition to the standard weld process control, a detailed process control (MWP-3) is issued for specific welding tasks which are complex and require actions to be taken during the welding process.
- b) Site Inspectors and Site ESS-DSD NDE inspectors have been instructed that specified inspections, which can not be completed as required, must be documented on a PIP for evaluation.
- c) Site QC Inspectors and Site ESS-DSD NDE inspectors have been instructed not to perform miscellaneous examinations without proper information defining the requirements of the examination.
- d) A form has been implemented to define the necessary information for miscellaneous inspections which are not specified by normal weld process control or site approved procedures. These forms are required to be completed by the requesting group to properly identify the inspection scope.
- e) A change to the Weld Isometric Revision Process ensures that appropriate revisions have been made and approved prior to field use.
- f) A second level review is now required to ensure that the correct NDE has been specified on QA Condition weld tickets.