

**Open Generic Communication TACs (PA No. 115126)  
Summary Report (AS OF 4/30/2015)**

| <b>TAC NO.</b> | <b>TAC TITLE</b>   | <b>AGE<br/>(Mon)</b> | <b>TAC<br/>OPENED</b> | <b>LEAD<br/>ORG</b> |
|----------------|--|----------------------|-----------------------|---------------------|
| ME9020         | RIS 'Embedded Digital Devices in Safety Systems'   | 34.0                 | 07/09/2012            | NRO                 |
| ME9843         | GL 'Treatment of Natural Phenomena Hazards At Fuel Cycle Facilities'                       | 31.0                 | 10/25/2012            | NMSS                |
| MF0581         | GL 'Degradation of Neutron Absorbing Material in Spent Fuel Pools'                         | 28.0                 | 01/29/2013            | DSS                 |
| MF0541         | RIS 'NRC Position on SSCs Requiring Protection from Tornado Missiles'                      | 28.0                 | 01/23/2013            | DSS                 |
| MF3182         | RIS 'Seismic Analysis Methods for Spent Fuel Dry Cask Loading Stack-up Configuration'      | 17.0                 | 12/05/2013            | NMSS                |
| MF3715         | RIS 'FY17 Planning for the Review of New Licensing Applications for Large LWR and SMR'     | 14.0                 | 03/31/2014            | DPR                 |
| MF3949         | RIS 'RIS 2005-29 Rev 1 Anticipated Transients That Could Develop into More Serious Events' | 13.0                 | 04/17/2014            | DSS                 |
| MF3996         | RIS 'Applicability of Branch Connection Butt Welds to ASME Code Case N-770'                | 13.0                 | 04/23/2014            | DE                  |
| MF4003         | RIS 'RIS 2005-20 Rev 2 Revision to NRC Inspection Manual Part 9900'                        | 13.0                 | 04/25/2014            | DSS                 |
| MF4346         | RIS 'Pressure Boundary Leakage'  | 11.0                 | 07/02/2014            | NRO                 |
| MF4394         | RIS 'Oversight of Counterfeit, Fraudulent, and Suspect Items in The Nuclear Industry'      | 10.0                 | 07/11/2014            | NRO                 |
| MF4697         | RIS 'Termination of Administrative Letter 93-01'   | 9.0                  | 08/27/2014            | DPR                 |
| MF4768         | IN 'Deficiencies with Effluent Radiation Monitoring System Instrumentation'                | 7.0                  | 09/07/2014            | NRR                 |

**Open Generic Communication TACs (PA No. 115126)  
Summary Report (AS OF 4/30/2015)**

| <b>TAC NO.</b> | <b>TAC TITLE</b>  | <b>AGE<br/>(Mon)</b> | <b>TAC<br/>OPENED</b> | <b>LEAD<br/>ORG</b> |
|----------------|---|----------------------|-----------------------|---------------------|
| MF5401         | IN 'Inoperable Auxiliary Feedwater Auto-Start Circuits on Loss of Main Feedwater Pumps' | 5.0                  | 12/12/2014            | DIRS                |
| MF5566         | IN 'Emerging Aging Degradation in Recirc. Piping in BWRS'                               | 4.0                  | 01/13/2015            | DE                  |
| MF5565         | RIS 'PCT Reporting Required by 50.46'   | 4.0                  | 01/13/2015            | DSS                 |
| MF5620         | RIS 'PAR for Members of Public on Bodies of Water'                                      | 3.0                  | 01/28/2015            | DPR                 |
| MF5661         | RIS 'Safety-Related SSCs in Service Beyond Service Life'                                | 3.0                  | 02/03/2015            | PGCB                |
| MF5772         | RIS 'Regulatory Requirements for Fingerprinting at Research and Test Reactors'          | 3.0                  | 02/23/2015            | PGCB                |
| MF5782         | RIS 'Accreditation Procurement of Laboratory Calibration and Test Services'             | 2.0                  | 02/25/2015            | PGCB                |
| MF5807         | RIS 'Preparation & Scheduling Annual Operator Licensing Examinations'                   | 2.0                  | 03/03/2015            | PGCB                |
| MF5828         | RIS 'UFSAR Submittals'  | 1.5                  | 03/10/2015            | PGCB                |
| MF5842         | RIS 'Clarification of Requirements in 10 CFR 50.59'                                     | 1.5                  | 03/12/2015            | PGCB                |
| MF5865         | IN 'Snubber Lubricant Degradation Issues'   | 1.5                  | 03/19/2015            | PGCB                |
| MF5876         | RIS 'PWR Steam Generator Tube-to-Tubesheet Weld Design Basis Issues'                    | 1.0                  | 03/20/2015            | PGCB                |
| MF6041         | RIS 'Crediting Mitigating Strategies in the SDP'  | 1.0                  | 03/31/2015            | PGCB                |

**Open Generic Communication TACs (PA No. 115126)  
Summary Report (AS OF 4/30/2015)**

| <b>TAC NO.</b> | <b>TAC TITLE</b>   | <b>AGE<br/>(Mon)</b> | <b>TAC<br/>OPENED</b> | <b>LEAD<br/>ORG</b> |
|----------------|--|----------------------|-----------------------|---------------------|
| MF6131         | RIS 'Clarification of the Requirements of 10 CFR 37.11b Specific Exemptions              | .1                   | 04/23/2015            | PGCB                |
| MF6150         | IN '10 CFR 50.59 Finding Regarding Circuit Board with Complex Programmable Logic Device' | .1                   | 04/28/2015            | PGCB                |