

## PMTurkeyCOLPEm Resource

---

**From:** Comar, Manny  
**Sent:** Thursday, June 04, 2015 4:55 PM  
**To:** TurkeyCOL Resource  
**Subject:** FW: Proposed Turkey Point, Units 6 and 7 - Correction of Evacuation Time Estimate - Revision 4 Figure H-23 Error.

---

**From:** Musico, Bruce  
**Sent:** Wednesday, May 06, 2015 9:56 AM  
**To:** Comar, Manny  
**Cc:** Barss, Dan  
**Subject:** RE: Proposed Turkey Point, Units 6 and 7 - Correction of Evacuation Time Estimate - Revision 4 Figure H-23 Error.

Yes, I will when I return to working on the SER (Dan forwarded it to me). This letter is currently profiled as non-public in ADAMS, and will need to be made public (by you?).

---

**From:** Comar, Manny  
**Sent:** Wednesday, May 06, 2015 9:40 AM  
**To:** Musico, Bruce  
**Cc:** Barss, Dan  
**Subject:** FW: Proposed Turkey Point, Units 6 and 7 - Correction of Evacuation Time Estimate - Revision 4 Figure H-23 Error.

Official copy and you can refer to it in the SER with ADAMs number

---

**From:** E-RIDS1 Resource  
**Sent:** Wednesday, May 06, 2015 9:24 AM  
**To:** Williamson, Alicia; Whited, Ryan; Tonacci, Mark; Sebrosky, Joseph; RidsRgn2MailCenter Resource; RidsManager Resource; Prescott, Peter; Nguyen, John-Chau; Minarik, Anthony; McGovern, Denise; Hughes, Brian; Habib, Donald; Goetz, Sujata; Galletta, Thomas; Comar, Manny; Butler, Rhonda; Barss, Dan; Anderson, Brian  
**Subject:** Proposed Turkey Point, Units 6 and 7 - Correction of Evacuation Time Estimate - Revision 4 Figure H-23 Error.

### ADAMS Distribution Notification

**D097 - Dockets 05200040 & 05200041 - Florida Power and Light Company AP1000 Turkey Point Units 6 and 7 SCOLA (Subsequent Combined License Application); related correspondence, etc**

[Open ADAMS P8 Document\(Proposed Turkey Point, Units 6 and 7 - Correction of Evacuation Time Estimate - Revision 4 Figure H-23 Error.\)](#)

[View ADAMS P8 Properties ML15119A011](#)

Accession Number	ML15119A011
Title	Proposed Turkey Point, Units 6 and 7 - Correction of Evacuation Time Estimate - Revision 4 Figure H-23 Error.
Docket Number	05200040 05200041
Document Date	04/27/2015

Author Name	Maher W
Author Affiliation	Florida Power & Light Co
Addressee Name	
Addressee Affiliation	NRC/Document Control Desk NRC/NRO
Document Type	Letter
Availability	Non-Publicly Available
Date to be Released	
Document Sensitivity	Non-Sensitive
Comment	
Date Added	04/29/2015
Keyword	DPCautoadd gjn1 MD 3.4 Non-Public B.2 Non-Public - Review for Release Upon Request tjb2

**Hearing Identifier:** TurkeyPoint\_COL\_Public  
**Email Number:** 1021

**Mail Envelope Properties** (377CB97DD54F0F4FAAC7E9FD88BCA6D0021FCCBDB50E)

**Subject:** FW: Proposed Turkey Point, Units 6 and 7 - Correction of Evacuation Time Estimate - Revision 4 Figure H-23 Error.  
**Sent Date:** 6/4/2015 4:54:36 PM  
**Received Date:** 6/4/2015 4:54:37 PM  
**From:** Comar, Manny

**Created By:** Manny.Comar@nrc.gov

**Recipients:**  
"TurkeyCOL Resource" <TurkeyCOL.Resource@nrc.gov>  
Tracking Status: None

**Post Office:** HQCLSTR01.nrc.gov

<b>Files</b>	<b>Size</b>	<b>Date &amp; Time</b>
MESSAGE	2602	6/4/2015 4:54:37 PM

**Options**  
**Priority:** Standard  
**Return Notification:** No  
**Reply Requested:** No  
**Sensitivity:** Normal  
**Expiration Date:**  
**Recipients Received:**