NRC FORM 591M PART 1 (07-2012)* 10 CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION		
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION				
LICENSEE/LOCATION INSPECTED: Magnum Midstream, LP 4481 Henderson Avenue Hickory, Pennsylvania 15340		NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713		
	2010001 & 2010002		5. DATES OF INSPECTIO	NNI .
3. DOCKET NUMBER: 03038732	37-35141-01	5)	05/19/2015, 07/07/20	
	07 00111 01		00/10/2010, 0//0//20	10, 017 10/2010
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X				
I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken,				
date when full compliance will be achi	,	ritten response to NRC will be		, ,
Title	Printed Name		Signature	Date
LICENSEE'S REPRESENTATIVE				
NRC INSPECTOR	Scott Wilson		/RA/	07/13/2015
BRANCH CHIEF	Blake Welling		/RA/	07/13/2015
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\WordDocs\Current\Insp Record\R37-35141-01.2015001-002.591Part1.doc				
SUNSI Review Completed By:	/ RA / SWilson		X Public X	Non-Sensitive