

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Owensboro Industrial Co., LLC 2 Plum Street, Owensboro, KY</p> <p>REPORT NUMBER(S)                      2015001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p><b>U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713</b></p>	
<p>3. DOCKET NUMBER(S)</p> <p>03038740</p>	<p>4. LICENSE NUMBER(S)</p> <p>16-35147-01E</p>	<p>5. DATE(S) OF INSPECTION</p> <p>July 16 and 23, 2015</p>

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

\_\_\_\_\_




4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

10 CFR 32.16(a) requires the licensee to submit a report to NRC by January 31 of each year, providing the information required by 10 CFR 32.16(b) for items transferred. 10 CFR 32.16(c) requires if no transfers of byproduct material have been made during the period, the report must so indicate. Contrary to the above, the licensee did not submit a report to the NRC by January 31, 2015, of byproduct material transferred in 2014.

On July 17, 2015, the licensee submitted the required report stating that no byproduct material was transferred during 2014. In addition, the licensee committed to take corrective action to assure that the required report will be submitted as required in the future, by scheduling the task for completion after the end of future calendar years.

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Mark Dohrenwend, RSO		July 29, 2015
NRC INSPECTOR	Todd J. Jackson, CHP		7/29/15
BRANCH CHIEF	Blake D. Welling		7/29/15