

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7812190153 DOC. DATE: 78/12/08 NOTARIZED: NO

DOCKET #  
05000287

FACIL: 50-287 OCONEE #3, DUKE POWER CO.

AUTH. NAME AUTHOR AFFILIATION

PARKER, W.O. DUKE POWER CO.

RECIP. NAME RECIPIENT AFFILIATION

O'REILLY, J.P. \*\*REG. 2, ATLANTA, OFF. OF THE DIRECTOR

7-31-78

SUBJECT: Forwards LER#78-015/03L-0. RPS Channel A, RC flow indication began reading high on 780729 & was valved out-of-svc on 780731 caused by leak in pressure transmitter impulse line. Leaking fittings were repaired.

DISTRIBUTION CODE: A002S. COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2

TITLE: INCIDENT REPORTS

NOTES: M CUNNINGHAM - ALL AMDTS TO FSAR + CHANGES TO TECH SPECS

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	05 BC <b>ORB #4</b>	4	4			
INTERNAL:	01 <b>REG FILE</b>	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 HANAUER	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 COLLINS	0	0	24 KREGER	1	1
	25 PWR SYS BR	1	1	26 HOUSTON	0	0
	26 VOLLMER	1	1	E JORDAN/IE	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	27 ACRS	16	16			

ccp

DEC 20 1978

A011-4

DEC 20 1978

TOTAL NUMBER OF COPIES REQUIRED: LTR 43 ENCL 43

REGULATORY DOCKET FILE COPY  
DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

December 8, 1978

TELEPHONE: AREA 704  
373-4083


Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

RE: Oconee Unit 3  
Docket No. 50-287

Dear Mr. O'Reilly:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station  
Technical Specifications, please find attached Reportable Occurrence  
Report RO-287/78-15.

Very truly yours,

  
William O. Parker, Jr.

KRW:ldh

Attachment

812190153

A002  
S/11

5