

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8102230667 DOC. DATE: 81/02/17 NOTARIZED: NO
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 AUTH. NAME: JONES, J.L. AUTHOR AFFILIATION: Duke Power Co.
 RECIP. NAME: REGION 2, Atlanta, Office of the Director

DOCKET # 05000269

SUBJECT: LER 81-002/03L-0: on 810118, DC input fuse in 1DID vital inverter blew during power reduction. Possibly caused by poorly made connections in logic cards edge connectors &/or intermitten component problems on logic cards.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2
 TITLE: Incident Reports

NOTES: M Cunningham: all amends to FSAR & changes to Tech Specs. 05000269
 AEOD, Ornstein: lcc.

ACTION:	RECIPIENT	COPIES	RECIPIENT		COPIES
	ID CODE/NAME		LTR	ENCL	
	REID, R. 04	3	3		
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1 1
	A/D MATL & QU08	1	1	A/D OP REACT009	1 1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1 1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1 1
	AEOD	3	3	ASLBP/J.HARD	1 1
	AUX SYS BR 15	1	1	CHEM ENG BR 16	1 1
	CONT SYS BR 17	1	1	CORE PERF BR 18	1 1
	DIR, DIV OF LIC	1	1	DIR, ENGINEER 20	1 1
	DIR, HUM FAC S21	1	1	DIR, SYS INTEG 22	1 1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1 1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1 1
	I&E 05	2	2	JORDAN, E./IE	1 1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1 1
	MECH ENG BR 33	1	1	MPA	3 3
	NRC PDR 02	1	1	OP EX EVAL BR34	3 3
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1 1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1 1
	REG FILE 01	1	1	REL & RISK A 41	1 1
	SFTY PROG. EVA42	1	1	STRUCT ENG BR44	1 1
	SYS INTERAC B45	1	1		
EXTERNAL:	ACRS 46	16	16	LPDR 03	1 1
	NSIC 05	1	1	TERA: DOUG MAY	1 1

FEB 25 1981

TOTAL NUMBER OF COPIES REQUIRED: LTR 69 ENCL 69