

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8709290146 DOC. DATE: 87/09/17 NOTARIZED: NO DOCKET #
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co. 05000269
 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co. 05000287

AUTH. NAME AUTHOR AFFILIATION
 TUCKER, H. B. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 GRACE, J. N. Region 2, Office of Director

SUBJECT: Advises that util in process of preparing & reviewing response to NRC 870818 request for addl info re IE Bulletin 85-003, "Motor-Operated Valve Common Mode Failure During Plant Transient." Response will be submitted by 871015.

DISTRIBUTION CODE: IE11D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Bulletin Response (50 DKT)

NOTES: AEOD/Ornstein:1cy. 05000269
 AEOD/Ornstein:1cy. 05000270
 AEOD/Ornstein:1cy. 05000287

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTR	ENCL		ID	CODE/NAME	LTR	ENCL
	PD2-3	LA	1	0		PD2-3	PD	1	1
	PASTIS,	H	1	1					
INTERNAL:	AEOD/DOA		1	1		AEOD/DSP		1	1
	AEOD/DSP/TPAB		1	1		NRR/DEST/ADE		1	1
	NRR/DEST/ADS		1	1		NRR/DEST/MEB		1	1
	NRR/DOEA/EAB		1	1		NRR/DOEA/GCB		1	1
	NRR/DREP/EPB		1	1		NRR/PMAS/ILRB		1	1
	REG-FILE	02	1	1		RES/DE/EIB		1	1
	RGN2 FILE	01	1	1					
EXTERNAL:	LPDR		1	1		NRC PDR		1	1
	NSIC		1	1					
NOTES:			1	1					

TOTAL NUMBER OF COPIES REQUIRED: LTR 20 ENCL 0

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

87 SEP 23 AIO: 57

September 17, 1987

Dr. J. Nelson Grace, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323


Subject: Oconee Nuclear Station
Docket Nos. 50-269, -270, -287
Request for Additional Information Concerning
Oconee's Response to IE Bulletin 85-03

Dear Sir:

By letter dated August 18, 1987 the NRC Staff requested additional information to continue their review of Duke Power Company's response to IE Bulletin 85-03, "Motor Operated Valve Common Mode Failure During Plant Transient Due to Improper Switch Settings". A response for additional information was requested within 30 days.

Duke Power Company is currently in the process of preparing and reviewing its response to the request for additional information. It is anticipated that a response will be provided no later than October 15, 1987.

Very truly yours,



Hal B. Tucker

MAH/77/sbn

Attachment

xc: Mr. J. C. Bryant
NRC Resident Inspector
Oconee Nuclear Station

Ms. Helen Pastis
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

8709290146 870917
PDR ADOCK 05000269
Q PDR

U.S. NRC - REGION 2
OFFICIAL COPY

IE11/0