

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

SAN ANTONIO TX NORTH FM GROUP
7503 Tezel Road
San Antonio, Texas 78250-3504

June 26, 2015

Director of FSME

Attn: GLTS

USNRC

Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on June 26, 2015 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2015. As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact Deana Childress 210 314-8162

Sincerely,



Deana Childress

Encl. Serial Number Spreadsheet



Clear

Save

Print

SERIAL NUMBER SPREADSHEET

| | | | |
|---------------|-------------------------------|----------------|---|
| Company Name | San Antonio TX North FM Group | Date | June 24, 2015 |
| Address 1 | 2103 St Cloud | Isolite RMA # | |
| Address 2 | | EWS Order # | 1150104401/1150094923/Disposal Only (3) |
| Address 3 | | MTS Order #s | 2430014401/2430094923/2430105275 |
| City/State | San Antonio | Contact Name | Deana Childress |
| Zip/Post Code | TX | Contact Phone | 210-314-8162 |
| Country | USA | Contact FAX | |
| | | Contact E-mail | fmd-san-antonio-tx-n-oa@ldschurch.org |

| | Manufacturer Name | Model No. | Serial No. | Manufacture Date | | Activity Include "Ci" or "TBq" |
|----|-------------------|---------------|---------------|------------------|------|-----------------------------------|
| | | | | Month | Year | |
| 1 | EVENLITE | not available | not available | 6 | 95 | not available |
| 2 | EVENLITE | not available | not available | 6 | 95 | not available |
| 3 | Not Available | not available | not available | NA | NA | not available |
| 4 | Safety Light Corp | 2040 | A54659 | 4 | 95 | 7.5 Ci |
| 5 | Not Available | not available | not available | na | na | not available |
| 6 | EVENLITE | 201 | 2359E | 6 | 95 | 10.5 Ci |
| 7 | EVENLITE | 201 | 5989D | 6 | 95 | 10.5 Ci |
| 8 | EVENLITE | 201 | 5993D | 11 | 94 | 10.5 Ci |
| 9 | EVENLITE | 201 | 2360E | 6 | 95 | 10.5 Ci |
| 10 | EVENLITE | 201 | 2364E | 6 | 95 | 10.5 Ci |
| 11 | EVENLITE | 201 | 5990D | 11 | 94 | 10.5 Ci |
| 12 | EVENLITE | 201 | 5994S | 11 | 94 | 10.5 Ci |
| 13 | EVENLITE | 201 | 2362E | 6 | 95 | 10.5 Ci |
| 14 | EVENLITE | 201 | 2361E | 6 | 95 | 10.5 Ci |
| 15 | EVENLITE | 201 | 2363E | 6 | 95 | 10.5 Ci |

Please fill in all the information required in the above columns. Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.



Clear

Save

Print

SERIAL NUMBER SPREADSHEET

| | | | |
|---------------|-------------------------------|----------------|---|
| Company Name | San Antonio TX North FM Group | Date | June 24, 2015 |
| Address 1 | 2103 St Cloud | Isolite RMA # | |
| Address 2 | | EWS Order # | 1150104401/1150094923/Disposal Only (3) |
| Address 3 | | MTS Order #s | 2430014401/2430094923/2430105275 |
| City/State | San Antonio | Contact Name | Deana Childress |
| Zip/Post Code | TX | Contact Phone | 210-314-8162 |
| Country | USA | Contact FAX | |
| | | Contact E-mail | fmd-san-antonio-tx-n-oa@ldschurch.org |

| | Manufacturer Name | Model No. | Serial No. | Manufacture Date | | Activity Include "Ci" or "TBq" |
|----|-------------------|---------------|---------------|------------------|------|-----------------------------------|
| | | | | Month | Year | |
| 1 | SRB TECH | U20 | 170966 | 1 | 94 | 20 Ci |
| 2 | SRB TECH | Not Available | Not Available | 1 | 94 | 20 Ci |
| 3 | SRB TECH | U20 | 170965 | 1 | 94 | 20 Ci |
| 4 | SRB TECH | U20 | 170961 | 1 | 94 | 20 Ci |
| 5 | SRB TECH | U20 | 170962 | 1 | 94 | 20 Ci |
| 6 | SRB TECH | U20 | 170963 | 1 | 94 | 20 Ci |
| 7 | EVENLITE | Not Available | Not Available | 6 | 95 | Not Available |
| 8 | EVENLITE | Not Available | Not Available | 6 | 95 | Not Available |
| 9 | Safety Light Corp | Not Available | Not Available | 7 | 2002 | Not Available |
| 10 | Safety Light Corp | Not Available | Not Available | 7 | 2002 | Not Available |
| 11 | Safety Light Corp | Not Available | Not Available | 7 | 2002 | Not Available |
| 12 | SRB Tech | B100 | 596101 | 9 | 95 | 20 Ci |
| 13 | SRB Tech | B100 | 596110 | 9 | 95 | 20 Ci |
| 14 | SRB Tech | B100 | 596109 | 9 | 95 | 20 Ci |
| 15 | SRB Tech | B100 | 596104 | 9 | 95 | 20 Ci |

Please fill in all the information required in the above columns. Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.



Clear

Save

Print

SERIAL NUMBER SPREADSHEET

| | | | |
|---------------|-------------------------------|----------------|---|
| Company Name | San Antonio TX North FM Group | Date | June 24, 2015 |
| Address 1 | 2103 St Cloud | Isolite RMA # | |
| Address 2 | | EWS Order # | 1150104401/1150094923/Disposal Only (3) |
| Address 3 | | MTS Order #s | 2430014401/2430094923/2430105275 |
| City/State | San Antonio | Contact Name | Deana Childress |
| Zip/Post Code | TX | Contact Phone | 210-314-8162 |
| Country | USA | Contact FAX | |
| | | Contact E-mail | fmd-san-antonio-tx-n-oa@ldschurch.org |

| | Manufacturer Name | Model No. | Serial No. | Manufacture Date | | Activity Include "Ci" or "TBq" |
|----|-------------------|---------------|---------------|------------------|------|-----------------------------------|
| | | | | Month | Year | |
| 1 | SRB Tech | B100 | 596107 | 9 | 95 | 20 Ci |
| 2 | SRB Tech | B100 | 596108 | 9 | 95 | 20 Ci |
| 3 | SRB Tech | B100 | 596105 | 9 | 95 | 20 Ci |
| 4 | SRB Tech | B100 | 596106 | 9 | 95 | 20 Ci |
| 5 | Safety Light Corp | not available | not available | 2 | 2002 | not available |
| 6 | | | | | | |
| 7 | | | | | | |
| 8 | | | | | | |
| 9 | | | | | | |
| 10 | | | | | | |
| 11 | | | | | | |
| 12 | | | | | | |
| 13 | | | | | | |
| 14 | | | | | | |
| 15 | | | | | | |

Please fill in all the information required in the above columns. Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.