FORD 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

R

Ι

D

S

0

R

D

D

0

C

U

М

Ε

N

T

FACIL:5 5 AUTH.N EBNETER RECIP.	0-269 Oconee Nuclea 0-270 Oconee Nuclea 0-287 Oconee Nuclea	r Station, r Station, r Station, FFILIATION (Post 82020 T AFFILIATI		Co.	DOCKET # 05000269 05000270 05000287
SUBJECT: Forwards initial SALP repts 50-269/93-11,50-270/93-11 & 50-287/93-11 for period 920202-930501.Performance maintained at superior level in areas of radiological protection & security.					
DISTRIBUTION CODE: IE40D COPIES RECEIVED:LTR ENCL SIZE:5+23 TITLE: Systematic Assessment of Licensee Performance (SALP) Report					
NOTES:					
	RECIPIENT ID CODE/NAME PD2-3 LA WIENS,L	COPIES LTTR ENCL 1 1 1 1		COPIES LTTR ENC 1 1	L
INTERNAL:	AEOD/DSP/TPAB DEDRO NRR/DRCH/HHFBPT NRR/DRIL/RPEB	2 2 1 1 1 1 1 1 1 1	AEOD/DOA COMMISSION NRR/DORS/OEAB NRR/DRCH/HOLB NRR/DRIL/RSIB	1 1 5 5 1 1 1 1 1 1	
	NRR/DRSS/PEPB	1 1	NRR/DRSS/PRPB	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

NRR/DRSS/RSGB

OGC/HDS2

RGN2

EXTERNAL: EG&G/BRYCE, J.H.

NRC PDR

NUDOCS-ABSTRACT

FILE 01

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK. ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

NRR/PMAS/ILRB

L ST LOBBY WARD

OE DIR

NSIC

REG FILE

1

1

1

1

02

1

1

1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 31

1

1

1

1

1

1

1

1

1

1

1

JUL 131993

Docket Nos. 50-269, 50-270 and

50-287

License Nos. DPR-38, DPR-47 and

DPR-55

Duke Power Company
ATTN: Mr. J. W. Hampton
Vice President
Oconee Site
P. O. Box 1439
Seneca, SC 29679

Gentlemen:

SUBJECT:

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

(NRC INSPECTION REPORT NOS. 50-269/93-11, 50-270/93-11 AND

50-287/93-11)

The NRC Systematic Assessment of Licensee Performance (SALP) has been completed for your Oconee facility. The facility was evaluated for the period February 2, 1992, through May 1, 1993. The results of the evaluation are documented in the enclosed Initial SALP Report. This report will be discussed with you at a public meeting to be held at the Oconee facility on July 28, 1993, at 10:00 a.m.

The performance of your Oconee facility was evaluated in the functional areas of Plant Operations, Radiological Controls, Maintenance/Surveillance, Emergency Preparedness, Security, Engineering/Technical Support, and Safety Assessment/Quality Verification.

Overall performance for Oconee continued with the same category ratings as the last assessment period. Performance was maintained at a superior level in the functional areas of Radiological Protection, Security and Emergency Preparedness. Performance in the remaining functional areas was good.

Although management attention resulted in improvement in command and control over operational evolutions, particularly shutdown operations, the weaknesses noted in the previous SALP period associated with procedural adherence continued. Failure by the staff to follow procedural requirements was compounded in some cases by the inadequacy of the procedures. Further, inadequate control of maintenance and surveillance activities resulted in several preventable operational transients. I look forward to discussing this assessment with you on July 28, 1993.

Any comments you have concerning our evaluation of performance of your Oconee facility should be submitted to this office within 30 days following the date of our meeting. Your comments will be considered in the development of the

Duke Power Company

2

Final SALP Report and will be issued, along with a summary of our meeting, as an appendix to the Final SALP Report.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

Original signed by Stewart Ehneter

Stewart D. Ebneter Regional Administrator

Enclosure: Initial SALP Report

cc w/encl:
M. E. Patrick
Compliance
Duke Power Company
P. O. Box 1439
Seneca, SC 29679

A. V. Carr, Esq. Duke Power Company 422 South Church Street Charlotte, NC 28242-0001

County Supervisor of Oconee County Walhalla, SC 29621

Robert B. Borsum
Babcock and Wilcox Company
Nuclear Power Generation Division
1700 Rockville Pike, Suite 525
Rockville, MD 20852

J. Michael McGarry, III, Esq. Winston and Strawn 1400 L Street, NW Washington, D. C. 20005

Office of Intergovernmental Relations 116 West Jones Street Raleigh, NC 27603

cc: Continued see page 3

3

cc: Continued
Heyward G. Shealy, Chief
Bureau of Radiological Health
South Carolina Department of Health
and Environmental Control
2600 Bull Street
Columbia, SC 29201

Manager, LIS NUS Corporation 2650 McCormick Drive Clearwater, FL 34619-1035

G. A. Copp
Licensing - EC050
Duke Power Company
P. O. Box 1006
Charlotte, NC 28201-1006

Karen E. Long Assistant Attorney General N. C. Department of Justice P. O. Box 629 Raleigh, NC 27602

INPO

4

bcc w/encl:

The Chairman

K. C. Rogers, Commissioner

F. J. Remick, Commissioner

E. G. de Planque, Commissioner

J. M. Taylor, EDO

H. L. Thompson, Jr., EDO

L. R. Plisco, Regional Coordinator, EDO

T. E. Murley, NRR

S. Varga, NŘŔ

D. B. Matthews, NRR

L. A. Wiens, NRR

F. Allenspach, SALP Coordinator, NRR

Regional Administrators, RI, RIII

RIV, and RV

K. Clark, RII, PAO

A. R. Herdt, DRP, RII

M. S. Lesser, DRP, RII

W. H. Miller, DRP, RII

S. Vias, Chief, TSS (2 copies)

NRC Resident Inspector DRS and DRSS Branch Chiefs,

and Section Chiefs

Document Control Desk

*FOR PREVIOUS CONCURRENCE SEE ATTACHED

RII RII RII RII RII *WMiller *MLesser *AHerdt * PSthor * JJaudon 07/ /93 07/ /93 07/ /93 07/ /93 07/ /93 RII NRR NRR *PHarmon LWiens **DMatthews** 07/ /93 07/ /93 07/ /93

Document Control Desk

bcc w/encl: The Chairman K. C. Rogers, Commissioner J. R. Curtiss, Commissioner
F. J. Remick, Commissioner
E. G. de Planque, Commissioner J. M. Kaylor, EDO H. L. Thompson, Jr., EDO J. F. Wechselberger, Regional Coordinator, EDO T. E. Murley, NRR S. Varga, NRR D. B. Matthews, NRR L. A. Wiens, WRR F. Allenspach, SALP Coordinator, NRR Regional Administrators, RI, RIII RIV, and RV K. Clark, RII, PAO A. R. Herdt, DRP, RII M. S. Lesser, DRP, RII W. H. Miller, DRP,\RII S. Vias, Chief, TSS (2 copies) NRC Resident Inspector DRS and DRSS Branch Chiefs, and Section Chiefs

ARH MĽěsser AHerdt WMiller 07/7/93 07/8 /93 07/8 /93 NRR & Kleghou RII RII NRR 🖈 RII pelephone Aff ĽWiens **DMatthews JJohnson** PHarmon LReyes 07/9/93 07/8/93 07/9 /93 07/ /93 07/ /93



UNITED STATES NUCLEAR REGULATORY COMMISSION REGION II 101 MARIETTA STREET, N.W., SUITE 2900 ATLANTA, GEORGIA 30323-0199

JUI 13 1993

Docket Nos. 50-269, 50-270 and

50-287

License Nos. DPR-38, DPR-47 and DPR-55

Duke Power Company
ATTN: Mr. J. W. Hampton
Vice President
Oconee Site

P. O. Box 1439 Seneca. SC 29679

Gentlemen:

SUBJECT:

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

(NRC INSPECTION REPORT NOS. 50-269/93-11, 50-270/93-11 AND

50-287/93-11)

The NRC Systematic Assessment of Licensee Performance (SALP) has been completed for your Oconee facility. The facility was evaluated for the period February 2, 1992, through May 1, 1993. The results of the evaluation are documented in the enclosed Initial SALP Report. This report will be discussed with you at a public meeting to be held at the Oconee facility on July 28, 1993, at 10:00 a.m.

The performance of your Oconee facility was evaluated in the functional areas of Plant Operations, Radiological Controls, Maintenance/Surveillance, Emergency Preparedness, Security, Engineering/Technical Support, and Safety Assessment/Ouality Verification.

Overall performance for Oconee continued with the same category ratings as the last assessment period. Performance was maintained at a superior level in the functional areas of Radiological Protection, Security and Emergency Preparedness. Performance in the remaining functional areas was good.

Although management attention resulted in improvement in command and control over operational evolutions, particularly shutdown operations, the weaknesses noted in the previous SALP period associated with procedural adherence continued. Failure by the staff to follow procedural requirements was compounded in some cases by the inadequacy of the procedures. Further, inadequate control of maintenance and surveillance activities resulted in several preventable operational transients. I look forward to discussing this assessment with you on July 28, 1993.

Any comments you have concerning our evaluation of performance of your Oconee facility should be submitted to this office within 30 days following the date of our meeting. Your comments will be considered in the development of the

9208050083

Final SALP Report and will be issued, along with a summary of our meeting, as an appendix to the Final SALP Report.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

Stewart D. Ebneter Regional Administrator

Enclosure: Initial SALP Report

cc w/encl:
M. E. Patrick
Compliance
Duke Power Company
P. O. Box 1439
Seneca, SC 29679

A. V. Carr, Esq.
Duke Power Company
422 South Church Street
Charlotte. NC 28242-0001

County Supervisor of Oconee County Walhalla, SC 29621

Robert B. Borsum
Babcock and Wilcox Company
Nuclear Power Generation Division
1700 Rockville Pike, Suite 525
Rockville, MD 20852

J. Michael McGarry, III, Esq. Winston and Strawn 1400 L Street, NW _ Washington, D. C. 20005

Office of Intergovernmental Relations 116 West Jones Street Raleigh, NC 27603

cc: Continued see page 3

cc: Continued
Heyward G. Shealy, Chief
Bureau of Radiological Health
South Carolina Department of Health
and Environmental Control
2600 Bull Street
Columbia, SC 29201

Manager, LIS NUS Corporation 2650 McCormick Drive Clearwater, FL 34619-1035

G. A. Copp Licensing - ECO50 Duke Power Company P. O. Box 1006 Charlotte, NC 28201-1006

Karen E. Long Assistant Attorney General N. C. Department of Justice P. O. Box 629 Raleigh, NC 27602

INPO