FACIL:50 Pr AGTH:NA FOSTER,V RECIP:1	N NBR:9706090218 D-270 Oconee Nuclea coject-693 Pabcock AME AUTHOR A M.W. Babcock & NAME RECIPIEN	INFORMATION DOC.DATE: 9 r Station, U & Wilcox Own FFILIATION Wilcox Oper T AFFILIATIO	Unit 2, Duke Power her's Group (B&WOG rating Plants Owne:	D: NO Co. ) Activitie rs Group	see 2	
DISTRIBU TITLE: 1	: Forwards FTI Docu HPI/MU Nozzle Cra info. UTION CODE: D045D Project 693 - Babco	cking," in s	IVED:LTR ENCL	request fo	2+87	C A T E
	RECIPIENT ID CODE/NAME NRR/DRPM/PGEB FILE CENTER OT NRR/DE NRR/DE NRR/DRPE NRR/DRPW RGN 1 RGN 3	COPIES LTTR ENCL 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	RECIPIENT ID CODE/NAME NRR/BIRMINGHAM NRR/DRCH NRR/DRPM/PECB NRR/DSSA RGN 2 RGN 4	COPIES LTTR ENC 1 1 1 1 1 1 1 1 1 1 1 1 1 1	CL	G O R Y 1
EXTERNAL:	NOAC	1 1	NRC PDR	1 1		D

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

0

C

U

Μ


Е

Ν

Т



Duke Power Company Entergy Operations, Inc. Florida Power Corporation Oconee 1, 2, 3 ANO–1 Crystal River 3



GPU Nuclear Corporation Toledo Edison Company Framatome Technologies, Inc. TMI–1 Davis-Besse

Working Together to Economically Provide Reliable and Safe Electrical Power

Suite 525 • 1700 Rockville Pike • Rockville, MD 20852 • (301) 230-2100

June 5, 1997 OG-1657

Project No. 693

Document Control Desk U. S. Nuclear Regulatory Commission Washington, DC 20555-0001

Attention: Mr. J. L. Birmingham, Project Manager Generic Issues and Environmental Projects Branch

Subject: B&WOG Report in Response to May 27, 1997 Request for Information

Reference: Letter to W. W. Foster (Duke Power Company) from J. L. Birmingham (US NRC), dated May 27, 1997; Subject: Request for Information Relative to the High Pressure Injection/Makeup Line Crack Found at Oconee Unit-2

Gentlemen:

TOP, PROJ

The referenced Request for Information letter was transmitted to me on May 27, 1997. Attached to the letter was a list of questions relating to the high pressure injection/makeup line crack found at Oconee Unit 2 and the generic implications for the other B&W Owners Group plants. It was agreed that an interim report would be provided with a partial response to the attached questions by June 6, 1997.

PROJ-693

030008

00270 PDR Attached are three copies (1 to the Document Control Desk and 2 to J. L. Birmingham) of "Interim B&W Owners Group Report on HPI/MU Nozzle Cracking," (FTI Document No. 51-5000239-00).

If you have any questions, please contact me at 869/885-3163 or Joe Kelly at 804/832-2964.

Very truly yours, K, For W. Foster, Chairman

B&WOG Steering Committee

## DUKE POWER COMPANY

JJK/bcc

c:

B&WOG Steering Committee						
J. A. Selva	-	Entergy Operations, Inc.				
R. C. Widell	-	Florida Power Corporation				
P. S. Walsh	-	GPU Nuclear, Inc.				
R. E. Donnellon	<b>`</b> –	Toledo Edison Company				
J. J. Kelly	-	Framatome Technologies, Inc./OF57				
-						
Jon Souto	-	Entergy Operations, Inc.				
Jon Souto K. C. Prasad	-	Entergy Operations, Inc. Toledo Edison Company				
	- - -					
K. C. Prasad	- - -	Toledo Edison Company				
K. C. Prasad Tim Brown	- - - -	Toledo Edison Company Duke Power Company				