NRC FORM 591M P	ART 1		U.S. NUC	CLEAR REGULATORY C	OMMISSION			
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION								
1. LICENSEE/LOCATION INSPECTED:			2. NRC/REGIONAL OFFICE					
Golden Valley M	Iemorial Hospital	Region III						
1600 North Seco	-		U. S. Nuclear Regulatory Commission					
Clinton, MO 647	735		2443 Warrenville Road, Suite 210					
			Lisle, IL 60532-4352					
REPORT NUMBER(s) 2015-001							
3. DOCKET NUMBER(S	5)	4. LICENSE NUMBE	R(S)	5. DATE(S) OF INSPECTION	-			
030-11317		24-16597-01		August 215	. 2015			
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:								
	the inspection findings, no violations v		mono o, mo mopostom vito mopo	John Manago and do nono				
2. Previous	Previous violation(s) closed.							
3. The viola non-repe								
	Non-cited violation(s) were discuss	sed involving the fol	lowing requirement(s):					
During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)								
Statement of Corrective Actions								
I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.								
TITLE	PRINTED NAME		SIGNATURE	,,,	DATE			
LICENSEE'S REPRESENTATIVE								
NRC INSPECTOR	Ryan Craffey		Refer Colorey		8/21/15			
BRANCH CHIEF	Aaron McCraw		JIML.		8 28 15			
NRC FORM 591M PART	1 (07-2012)	9			11			

NRC FORM 591M PART 3 (07-2012) 10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION							
1. LICENSEE/LOCATION INS	SPECTED:		2. NRC/REGIONAL OFFICE				
Golden Valley Memorial Hospital 1600 North Second Street Clinton, MO 64735			Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352				
REPORT NUMBER(S) 2	015-001			TO THE PROPERTY OF THE PROPERT			
3. DOCKET NUMBER(S)		4. LICENSE NUMBER((S)	5. DATE(S) OF INSPECTION			
030-11317		24-16597-01		August 21, 2015			
6. INSPECTION PROCEDURES USED		7. INSPECTION FOCU	7. INSPECTION FOCUS AREAS				
87131		All	All				
SUPPLEMENTAL INSPECTION INFORMATION							
1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTAC	СТ	4. TELEPHONE NUMBER			
02120	3	Michael Gilbert,	, DO - RSO	(660) 885-5511			
✓ Main Office Inspection		Next Inspection	n Date: 08/21/20	18			
Field Office In	spection						
Temporary Jo	b Site Inspection _						
		DDOCDAM S	CORE	A STATE OF THE STA			

PROGRAM SCOPE

This was an unannounced routine inspection of a community hospital authorized to perform diagnostic and therapeutic administrations of radiopharmaceuticals at its facility in Clinton, Missouri. At the time of the inspection, three nuclear medicine technologists performed approximately six diagnostic administrations per day, Monday through Friday. The licensee received authorization for therapeutic administrations in May 2014, after removing a previous authorization for therapies in November 2012. The licensee has not yet performed any therapies since adding the authorization back onto its license. The licensee was also planning on moving the department in about a year to a new wing of the hospital currently under construction. The inspector reminded the licensee's technologists of the need to notify the NRC of this change in accordance with 10 CFR 35.14(b)(5). The technologist said that they would discuss this with their contract medical physicist. The inspector also found that a contract mobile nuclear medicine licensee performed mobile PET scans on-site every Wednesday morning.

PERFORMANCE OBSERVATIONS

The inspector toured the nuclear medicine department to evaluate the licensee's measures for materials security, hazard communication and exposure control. The inspector conducted independent and confirmatory surveys of the facilities, and found no exposures to members of the public in excess of regulatory limits. The inspector identified the presence of slight contamination on the injection chair, and observed the technologists as they implemented licensee procedures for spill response. The inspector also observed the preparation and administration of two cardiac stress tests using Tc-99m, as well as demonstrations by licensee staff of package receipt, administration of Xe-133 for lung studies, waste handing, area surveys, the conduct of hazmat training and the administration of radiopharmaceuticals requiring a written directive, including patient release. Through these observations, demonstrations, and discussions, the inspector found the licensee's staff to be knowledgeable of regulatory requirements and licensee procedures.

The inspector also reviewed all I-131 written directives for therapeutic administration conducted since the last inspection but before the modality was removed in November 2012. The inspector also reviewed a selection of available nuclear medicine records, including those for package receipt, dose administration, area surveys and waste handling. No violations of NRC requirements were identified as a result of this inspection.