

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Morgar CSP dba Carolina Cardiovascular Diagnostics P.O. Box 11665 Santurce, Puerto Rico 00910 REPORT NUMBER 2015001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER 030-38493	4. LICENSE NUMBER 52-31455-01	5. DATE OF INSPECTION August 5, 2015	

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s) and corrective action(s):

4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with the NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

10 CFR 20.1501(a) requires, in part, that each licensee shall make surveys of areas that may be necessary for the licensee to comply with the regulations in this part and are reasonable under the circumstances to evaluate the potential radiological hazard of the residual radioactivity detected.

Contrary to the above, on August 5, 2015, the licensee did not make a survey of an area to evaluate the potential radiological hazard of any residual radioactivity that may be present. Specifically, the nuclear medicine technologist conducted a survey of the treadmill area that was not adequate because it failed to detect contamination in an unlabeled sharps container and a table surface.

This is a Severity Level IV violation (Section 6.7)

(continued on page 2)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	David Rhoe	<i>David Rhoe</i>	8/26/15
NRC INSPECTOR	Shawn W. Seeley	<i>Shawn W. Seeley</i>	8/27/15
BRANCH CHIEF	<i>James P. Dwyer</i>	<i>[Signature]</i>	

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED; Morgar CSP dba Carolina Cardiovascular Diagnostics P.O. Box 11665 Santurce, Puerto Rico 00910 REPORT NUMBER 2015001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713	
3. DOCKET NUMBER 030-38493	4. LICENSE NUMBER 52-31455-01	5. DATE OF INSPECTION August 5, 2015	

(Continued)

10 CFR 20.1904(a) requires in part, the licensee to ensure that each container of licensed material bears a durable, clearly visible label bearing the words "CAUTION, RADIOACTIVE MATERIAL," or "DANGER, RADIOACTIVE MATERIAL."

Contrary to the above, on August 5, 2015, a container containing licensed material did not bear a durable, clearly visible label bearing the words "CAUTION, RADIOACTIVE MATERIAL." Specifically, a container of biohazard sharps did not bear a CAUTION, RADIOACTIVE MATERIAL label informing individuals handling the container or working in the vicinity of the container that necessary precautions needed to be taken to avoid or minimize exposure.

This is a Severity Level IV violation (Section 6.3)

Corrective actions were taken by the licensee as follows:

The treadmill room was posted with a "Radioactive Materials" sign; the sharps container was labelled as containing radioactive material; the table was decontaminated; and the batteries were scheduled to be changed the following day to ensure an adequate survey could be conducted.