

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

August 20, 1979

TELEPHONE: AREA 704
373-4083

Mr. James P. O'Reilly, Director
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, GA 30303

Re: Oconee Unit 1
Docket No. 50-269

Dear Mr. O'Reilly:

My letter of August 6, 1979, provided preliminary details of an incident which involved a steam generator tube leak. Please find attached Reportable Occurrence Report RO-269/79-24, which provides a more complete description of that incident. This report is being submitted pursuant to Oconee Nuclear Station Technical Specifications 6.2 and 6.6.2.1.a(3), which concerns degradation in a reactor coolant system boundary, and describes an incident which is considered to have no significance with respect to its effect on the health and safety of the public.

Very truly yours,

William O. Parker, Jr.

William O. Parker, Jr. *By [Signature]*

SRL/sch

Attachment

cc: Director, Office of Management Information
and Program Control



*1002
5/11*

2908240389